



GAGE TO CHECK 5/8" POINT WEAR ON CONFORMAL FROGS



CONFORMAL GAGE FOR CHECKING TREAD WEAR AND FLANGEWAY DEPTH AT POINT



CONFORMAL GAGE FOR CHECKING TREAD WEAR AND FLANGEWAY DEPTH AT 1 % 'SPREAD