



PARTS LIST	
1	LINEAR ACTUATOR - AMAZON
2	LOAD CELL - AMAZON
3	LOAD CELL JAW - 3D PRINTED
4	TESTER HOUSING - 3D PRINTED
5	ACTUATOR JAW - 3D PRINTED
6	TEST SAMPLE - 3D PRINTED
7	M3 X 14mm MCMaster 92832A566
8	M3 X 20mm MCMaster 92832A229
9	M6 x 30mm GRUB SCREW MCMaster 91390A136
10	ACTUATOR SUPPORT - 3D PRINTED



<p>PROPRIETARY AND CONFIDENTIAL</p> <p>THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF PROTOPLANT INC.. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF GIVMAR INC. IS PROHIBITED.</p>	UNLESS OTHERWISE SPECIFIED:		NAME	DATE			
	DIMENSIONS ARE IN INCHES TOLERANCES: ANGULAR: MATCH ± BEND ± TWO PLACE DECIMAL ±.010 THREE PLACE DECIMAL ±.005				DRAWN	D.H.C	2/9/2024
	MATERIAL	COMMENTS:			SIZE	DWG. NO.	REV
	FINISH				A	Layer Adhesion tester exp	—
	DO NOT SCALE DRAWING				SCALE: 1:8	WEIGHT: N/A	SHEET 1 OF 1