




- The headset should be stored in a dry place Avoid contact with water, moisture &
- dust. It may affect the performance. • To ensure a smooth connection, Keep the headset and your device within 10m.
- Avoid Dropping.
- Do not disassemble.
- Do not submerge in water.
- Avoid extreme temperature.
- Do not use the device outdoors during a thunderstorm.
- Use original or certified cables.
- Do not use any corrosive cleaner/oil to
- clean.
- Do not overcharge your product.

1

HEARING SAFETY

-To avoid hearing damage, do not listen for extended periods at high volume. -Do not turn the volume so high that you're unable to hear your surroundings. -You should use the caution or temporarily discontinue use in potentially hazardous situation.





OVERVIEW OF HEADSET

M.F.B. Mic 6

4

USB Port

USING YOUR HOPPUP RUSH

1. POWER ON

 Long press the MFB for 5 seconds to turn on the device.

2. POWER OFF

 Long press the MFB for 5 seconds to turn off the device.

3. CHARGE

- The red light flashes when the battery level is low.
- When the device is charging , the red LED light will
- be ON. • When device is fully charged , the blue LED light will
- be ON.

4. BLUETOOTH PAIRING

 When the device is ON, the blue and red LED lights flash alternatively , it means the device is ready to pair.

5