# REGAL<sup>®</sup> HIGH SPARKLE METALLIC

Primax Regal High Sparkle Metallic Paint is a high gloss, high sparkle, and high luster paint with beautiful colors. It gives a very special look to the object painted with Primax High Sparkle Metallic Paint. It can be used for Steel and wood structures, furniture, fans, electric panels, toys, doors, and windows.

**PACK SIZE:** 0.91L 3.64L

COLOR RANGE: See the appropriate shade card

## **COMPOSITION (NOMINAL):**

Pigment: High sparkle aluminum

Binder: Alkyd Resin

Solvent: Mineral Turpentine / Super Petrol

#### **DRYING TIME:**

Depends on temperature humidity, air movements, and film thickness

Touch Dry: 2-4 Hours

Recoat: 6-8 Hours

## THEORETICAL COVERAGE:

A guide to the theoretical coverage which can be achieved under normal conditions is 11-12m2/liter/coat.

#### FLASH POINT:

36\*C

**APPLICATION:** Spray, Brush

#### THINNING:

Brush: 10-15%

Conventional spray 20-25 %

## **CLEANING UP:**

Clean all equipment with mineral turpentine/super petrol immediately after use.

## **SURFACE PREPARATION:**

Scuff the surface with the sandpaper. Remove all dirt, and grease by air blow and wipe with a rag soaked in white spirit. Apply one coat of Primax Synthetic Undercoat, scuff, and clear, and then apply Primax High Sparkle Metallic Paint in two coats with suitable intervals.



## SAFETY, HEALTH, AND ENVIRONMENTAL INFORMATION:

Keep the container tightly closed and upright to prevent leakage when not in use. Don't breathe in vapors and sanding dust. A cartridge mask should be worn when rubbing down. Provide adequate ventilation during application and drying. If you experience difficulty in breathing, move to fresh air. Don't permit smoking in the vicinity. Avoid contact with eyes and skin. Wear gloves and goggles during application or sanding. In case of contact with eyes, flush with plenty of water and seek medical advice. To remove splashes from the skin, use soap and water or a recognized skin cleaner. Protect from extremes of temperatures. Store in a cool dry place but also protect from freezing. In case of fire, use foam, dry powder, CO2 fire extinguisher. Keep away from the source of ignition. Close the container tightly after each use. Keep out of reach of children. In case of an accident, collect spillage using sand or clay and dispose of paint waste in accordance with appropriate environmental quality requirements.

Any advice recommendations, information, assistance, or service provided by Progressive Paint Industries in relation to goods manufactured or marketed by it or their use or any applications is given in good faith without expressed or implied warranties.

# NOTE:

Color and high sparkle metallic finish depend very much on the right pressure, the distance between the spray gun and the surface, the viscosity of the paint, method of application of the painter.

