

# REGAL<sup>®</sup> SYNTHETIC METALLIC

Primax Regal Synthetic Metallic is suitable for correctly primed wood and metal surfaces. Due to its good weather resistance, it may be used as a topcoat on steel, iron, zinc, wood, galvanized substrates, etc.

**PACK SIZE:** 0.91L 3.64L

**COLOR RANGE:** See the appropriate shade card

## **COMPOSITION (NOMINAL):**

Pigment: Colorfast and metallic Pigments

Binder: Modified Alkyd Resin

Solvent: Mineral Turpentine / Super Petrol

## **DRYING TIME:**

Depends on temperature humidity, air movements, and film thickness

Touch Dry: 2-4 Hours

Recoat: 6-8 Hours

## **THEORETICAL COVERAGE:**

A guide to the theoretical coverage which can be achieved under normal conditions is 12-14m<sup>2</sup>/liter/coat.

## **FLASH POINT:**

36°C

## **APPLICATION:**

Spray

## **THINNING:**

Brush: 10-15%

Conventional spray 20-25 %

## **CLEANING UP:**

Clean all equipment with Thinner/Cleaner PRIMAX Mixing Oil /super petrol immediately after use.

## **SURFACE PREPARATION:**

The substrate must be sound, clean, dry, free from dust, oil, grease, and laitance, etc. All traces of release agents must be removed. On chalky and dusty surfaces, all loose material must be removed by stiff bristle brushing.



**PRIMAX**<sup>TM</sup>  
**PAINTS**

**TYPICAL PAINT SYSTEM:**

PRIMAX Undercoat 1-2 coat

PRIMAX Metallic Finish 1-2 coat

Other systems may be specified, depending on the area of use

**SAFETY, HEALTH AND ENVIRONMENTAL INFORMATION:**

Keep container tightly closed and upright to prevent leakage when not in use. Don't breathe in vapors and sanding dust. Cartridge mask should be worn when rubbing down. Provide adequate ventilation during application and drying. If you experience difficulty in breathing, move to fresh air. Don't permit smoking in the vicinity. Avoid contacts with eyes and skin.

Wear gloves and goggles during application or sanding. In case of contact with eyes, flush with plenty of water and seek medical advice. To remove splashes from skin, use soap and water or recognized skin cleaner. Protect from extremes of temperatures. Store in a cool dry place but also protect from freezing. In case of fire, use foam, dry powder, CO2 fire extinguisher. Keep away from source of ignition. Close container tightly after each use. Keep out of reach of children. In case of accident, collect spillage using sand or clay and dispose off paint waste in accordance with appropriate environmental quality requirements.

Any advice recommendations, information, assistance or service provided by Progressive Paint Industries in relation to goods manufactured or marketed by it or their use or any applications is given in good faith without expressed or implied warranties.



**PRIMAX**<sup>TM</sup>  
**PAINTS**