

Web: www.Lasersmith.co.uk E: Admin@Lasersmith.co.uk Tel: 02891 246356

Assembly Diagram: J008 - Santa Sleigh Freestanding

Always dry fit first then use a suitable wood adhesive before painting the sleigh

Step 1 - Lay out pieces as shown for dry fitting



Step 2 - Once you are happy with the layout take the centre pieces and place them into the side panel. Gluing them into place one at a time



Step 3 - Glue on the second side panel. The sleigh is complete.