

CALCIUM HARDNESS TEST PROCEDURE

The Calcium Hardness test procedure utilizes the **STANDARD STRIP METHOD** using the eXact iDip® Smart Photometer System®. For tips on achieving best accuracy, and additional information regarding features of the eXact iDip® photometer and the eXact iDip® app, please refer to the eXact iDip® Smart Guide. You can download a copy on our website at exactidip.com. **Test procedures can vary from test to test. Read full instructions and watch instructional video within the app.**

YOU WILL NEED

- eXact iDip® photometer
- Your smartphone/tablet with the eXact iDip® app installed and Calcium CA test purchased in the Store
- (1) eXact® Strip Micro Calcium Hardness (Part No. 486629)
- Water sample for rinsing and testing

SELECT CUSTOMER

- a. Select 'Customers' from the Home screen.
- b. Choose customer from list


OR Tap 'Add customer from contacts' and choose customer from your contacts list

OR Tap '+' to create a new customer

Android users: If no address is found, tap "No addresses found"

c. Verify customer has been selected

Note: To take full advantage of the GPS and Data Storage features, each test result must be linked to a contact. Individual users may select their contact listing.



POWER ON EXACT IDIP®

Press the TERO/ON button to power on the eXact iDip® photometer.

SELECT BLUETOOTH TEST

Tap the menu slide out '\equiv and select 'Bluetooth Test' from the choices shown.



4

CONNECT EXACT IDIP®

The eXact iDip® app will automatically connect to the most recently used eXact iDip® photometer. If not, select your eXact iDip® from the bottom of the screen.

Note: Always connect your eXact iDip® photometer via the Bluetooth® connection within the app. If you experience an issue connecting your device, check that your smartphone/tablet's Bluetooth® is turned on and your device is compatible.



5 Ta

SELECT TEST


Tap '**SELECT** Test' at the top and select **Calcium CA** (if this is not visible, purchase the test from the Store). The eXact iDip® photometer and eXact iDip® app will both display the test selection for Calcium Hardness.



6

FILL CELL

Before testing, rinse CELL and clean with brush thoroughly. Finally, rinse the cell 3 times with the water sample to be tested, then **FILL** cell to capacity to begin test (refer to video in app).



CAP CELL AND ZERO METER

Place the Cell Cover onto the CELL and press (EROJO) and the eXact iDip® photometer display reads OPPM indicating the meter is ready for testing.



REMOVE STRIP

Remove one eXact® Strip Micro Calcium Hardness (Part No. 486629) and set in a dry, convenient place. Immediately replace cap on bottle.




DIP STRIP

Press **READ** to initiate a 20 second countdown and simultaneously **DIP** the eXact® strip in the sample, **gently touching the bottom of the cell. Even if all pads are not immersed in water, do not bend the strip.** Use a gentle constant back and forth motion (2 strokes per second) until the timer displays "1". Be careful while dipping the strip. Do not spill the sample from the CELL. Remove and discard the strip.



CAP CELL AND READ RESULTS

Place the Cell Cover onto the CELL and **READ** result displayed as Calcium Hardness.





11

CLEAN CELL WITH BRUSH

After testing, rinse CELL immediately and clean with brush to remove reagents which coat the CELL wall.



TIPS

- Due to the manufacturing process, you may find one or two strips that are noticeably smaller or larger in width than the normal strips in the bottle. These should be discarded. Using these strips may give unreliable results.
- Before running test unlock Calcium Hardness test by purchasing in the Store.
- To obtain optimal accuracy when testing in direct sunlight, use the Mixing Cap/Cell Cover when zeroing and reading the sample.
- For water temperatures above 95°F/35°C (hot tubs), remove the strip when the timer displays "10", or use the specially calibrated test "SPA Calcium" test method available in the eXact iDip® Store.
- It is recommended to use the Cell Cleaning Brush with water to clean the CELL after each test to remove reagents which coat the CELL wall.
- Even if all pads are not immersed in water, do not bend the strip. Make sure the strip touches the bottom of the CELL while dipping the strip for 20 seconds.
- Be careful while dipping the strip (step 9). Do not spill the sample from the CELL.
- This test is accurate in water with Salt <2,500 ppm as NaCl. Salt levels from 2,500 to 33,000 ppm as NaCl give 10-15% error. For samples with Salt levels greater than 33,000 ppm as NaCl, contact ITS.

MANAGE YOUR RESULTS

Save, send, and share results instantly using the eXact iDip® app. For step-by-step instructions, refer to the eXact iDip® Smart Guide. You can download a pdf copy on-line at exactidip.com.

