LAUNDRY SYMBOLS (Iron and Dry Clean)



••

60°

95°

Machine wash

Machine wash,

gentle/delicate

laundered only on the

Garment may be machine

setting designed for gentle

agitation and/or reduced

Garment may be laundered through the use of hottest available water, detergent or soap, agitation, and a machine designed for this purpose.




Machine wash. permanent press

Garment may be machine laundered only on the setting designed to preserve Permanent Press with cool down or cold rinse prior to reduced spin.



Hand Wash


Garment may be laundered through the use of water, detergent or soap and gentle hand manipulation.





Do not wring

Do not wring the garment.



Water Temperature

Initial water temperature should not exceed 40C or

Water Temperature

Initial water temperature

should not exceed 60C or

Water Temperature

Initial water temperature

should not exceed 95C or



30°

Water Temperature

Initial water temperature should not exceed 30C or 65 to 85F.

Water Temperature

Initial water temperature

should not exceed 50C or

Water Temperature

Initial water temperature

should not exceed 70C or

120F.

160F.



50°

\•••/

70°

Hang to dry

Heat setting.

Hang damp garment from



line or bar, in or out doors.




Dry in the shade

Usually added to Line or Drip Dry. Dry away from

A machine dryer may not

alternate drying method



Do not dry

be used. Usually

symbol.

accompanied by an

from line or bar, in or out doors, without hand shaping or smoothing.



Do not tumble dry

A machine dryer may not be used. Usually accompanied by an alternate drying method



Tumble dry, gentle

A machine dryer may be regularly used only at the gentle setting.



Tumble dry. permanent press

A machine dryer may be regularly used only at the



Iron, Any Temperature. Steam or Dry

Regular ironing may be needed and may be performed at any available temperature with or without steam is acceptable.



••

Do not Iron

Item may not be smoothed or finished with an iron.



Maximum Temperature 110°C

Regular ironing, steam or dry, may be performed at Low setting (110C, 230F)



Maximum Temperature 150°C

Regular ironing, steam or dry, may be performed at Medium setting (150C, 300F).



Maximum Temperature 200°C

Regular ironing, steam or dry, may be performed at High setting (200C, 290F).



No steam

Steam ironing will harm garment, but regular dry ironing at indicated temperature setting is acceptable.



Maximum Temperature 200°C

Dry Clean, any solvent, any cycle any moisture, any heat.



Maximum Temperature 200°C

Garment may not be commercially dry cleaned.



Dry clean, any solvent except Trichloroethylene

Any dry cleaning solvent other than trichloroethylene may be safely used.



Dry clean, any solvent

Dry Clean, any solvent. Usually used with other restrictions on proper dry cleaning procedure.



Wet cleaning

Non-toxic, environmentally safe alternative to dry cleaning



Dryclean, petroleum solvent only

Dry Clean using only petroleum solvent. Usually used with other restrictions.



Dry clean, reduced moisture

May be used with A, P, or F solvent restriction.



Dry clean, no steam

May be used with A, P, or F solvent restriction.



Dry clean, short cycle

May be used with A, P, or F solvent restriction.



Dryclean, no heat

May be used with A, P, or F solvent restriction.





Bleach if needed

Any commercially available bleach product may be used in the laundering process.



heat)

setting.

heat)

Non-Chlorine

Only a non-chlorine, colorsafe bleach may be used in the laundering process. Chlorine bleach may not be

Dry normal (low

A machine dryer may be

maximum of Low Heat

Dry normal (high

A machine dryer may be

regularly used at a High

regularly used at a



Dry normal (medium heat)

Do not bleach

Tumble dry

setting.

used. The garment is not

to withstand any bleach.

A machine dryer may be

available temperature

regularly used at the hottest


colorfast or structurally able

A machine dryer may be regularly used at a maximum of Medium Heat setting.



Dry normal (no heat)

Initial water temperature should not exceed 30C or 65 to 85F.



Dry flat

Lay out horizontally for drying.



Drip dry

Hang dripping wet garment



symbol.



permanent press setting.