

IPC-T32IR-ZAS

Leo V2.800.0000000.43.R.230829

Release Notes

Table of Contents

Legal Information.....	1
1 Release Notes	3
1.1 Overview.....	3
1.2 New Features.....	3
1.3 Fixed Bugs.....	3
1.4 Compatibility.....	4
1.4.1 Program.....	4
1.4.2 Browser.....	4
1.4.3 Third-party Access.....	4
1.5 Software Environment.....	4
1.6 Pending Issues.....	5
1.7 Update Guide.....	5

1 Release Notes

1.1 Overview

Product name	Leo products
Version	V2.800.0000000.43.R.230829
Software package information	<p>DH_IPC-HX2(5)XXX-Leo_MultiLang_PN_Stream2_V2.800.0000000.43.R.230829.zip</p> <p>DH_IPC-HX3XXX-Leo_MultiLang_NP_Stream3_V2.800.0000000.43.R.230829.zip</p> <p>DH_IPC-HX3XXX-Leo_MultiLang_PN_Stream3_V2.800.0000000.43.R.230829.zip</p> <p>DH_IPC-HX5(4)(3)XXX-Leo_MultiLang_NP_Stream3_V2.800.0000000.43.R.230829.zip</p> <p>DH_IPC-HX5(4)(3)XXX-Leo_MultiLang_PN_Stream3_V2.800.0000000.43.R.230829.zip</p> <p>DH_IPC-HX5(4)(3)XXX-Leo_MultiLang_NP_Stream3-USA_V2.800.0000000.43.R.230829.zip</p> <p>DH_IPC-EX5XXX-Leo_MultiLang_NP_Stream3_V2.800.0000000.43.R.230829.zip</p> <p>DH_IPC-EX5XXX-Leo_MultiLang_PN_Stream3_V2.800.0000000.43.R.230829.zip</p> <p>DH_IPC-EX5XXX-Leo_MultiLang_NP_Stream3-USA_V2.800.0000000.43.R.230829.zip</p> <p>DH_IPC-HX5(4)XXXL-Leo_MultiLang_PN_Stream3_V2.800.0000000.43.R.230829.zip</p>
OS requirement	None
Release date	September 13, 2023

1.2 New Features

No.	Feature Description
1	Update the face detection algorithm. Face false alarms are reduced and face effect is optimized.

1.3 Fixed Bugs

No.	Bug Description
1	Fixed general historical issues.

1.4 Compatibility

1.4.1 Program

This is a revised version, which is compatible with later versions.

1.4.2 Browser

Chrome: 21.0.1180.11, 86.0.4240.198

IE: IE 9, IE 11

Firefox: 34.0.5.5443, 82.0.3

1.4.3 Third-party Access

1. ONVIF testing tool version: V20.06
2. ONVIF: Supports Profile G
3. MILESTONE testing tool: Milestone XProtect Corporate 2019 R2
4. GENETEC testing tool: Security Center Version 5.7SR1 (5.7.529.12)

1.5 Software Environment

Category	Model	Version
NVR	NVR4X-4KS2	2.6.02.02.00495 DH_NVR4XXX-4KS2_MultiLang_V4.001.0000003.1.R.200813.zip
	NVR5X-4KS2	2.6.01.02.08557 DH_NVR5XXX-4KS2_MultiLang_V4.001.0000003.1.R.200813.zip
	NVR4X-I	2.6.01.02.08571 DH_NVR4XXX-I_MultiLang_V4.001.0000000.2.R.200814.zip
	NVR5X-I	2.6.01.02.08563 DH_NVR5XXX-I_MultiLang_V4.001.0000000.2.R.200814.zip
EVS	EVS7X	2.6.01.02.07268 DH_EVS71XX_Eng_V4.001.0000000.2.R.200514.BIN
IVSS	IVSS7X	2.6.01.02.07976 DH_IVSS7XX_Eng_V2.001.0000000.0.R.200703.BIN
App	DMSS	General_DMSS-Android-Phone_MultiLang_Basic_IS_V1.000.0000002.2.R.200408
Tool	SmartPlayer	2.8.02.01.00303 General_SmartPlayer-Win32_Eng_IS_V4.000.0000001.4.R.191009.zip

Category	Model	Version
	ConfigTool	2.8.02.01.01140 General_ConfigTool_ChnEng_V5.001.0000002.0.R.20230223.zip
	SmartPSS	2.7.05.01.00850 DH_SMARTPSS- Win64_ChnEng_IS_V2.003.0000002.1.R.200602.Bugix.zip

1.6 Pending Issues

None.

1.7 Update Guide

1. Do not disconnect the network, reboot or turn off the camera during update.
2. When updating with the false file, you need to reboot the device, otherwise some functions might be disabled.

ENABLING A SAFER SOCIETY AND SMARTER LIVING