



SPAL BRUSHLESS  
12VDC MOTOR FAN



SBL-YAZ-PT  
Yellow Wire Not Used.

SPAL BRUSHLESS  
12VDC MOTOR FAN




SBL-YAZ-PT  
Yellow Wire Not Used.

Chassis Ground  
\*Sensor Ground at the same location as the fans ground.

Splice the White wires together from the fans to the sensor.

SBL-TS-HARN

Spal Brushless Fan Sensor




5 AMP FUSE  
FUSED SWITCHED IGNITION SOURCE



OPTIONAL OVERRIDE SWITCH (POSITIVE TRIGGER)  
12 VDC(+) Switch on gives full speed.

FUSE HOLDER WITH  
MAXI STYLE FUSE

NOTE: A DIFFERENT FUSE VALUE MAY BE  
REQUIRED DEPENDENT UPON THE SPAL  
BRUSHLESS MOTOR FAN BEING USED.



Chassis Ground