

**FOR THERMOLITE COLLECTOR  
USE LOCKING COLLARS FOR ATTACHING COLLECTOR TO  
MANIFOLDS AND JOINING BARBS**

**DIRECTIONS:** STRIP BACK COLLECTOR BACKING (APPROX 40mm) AND SLIDE LOCKING COLLAR OVER TUBE. PUSH TUBE ON MANIFOLD BARBS OR SINGLE JOINING BARB (push tube on to about 2nd barb) AND SLIDE COLLAR OVER MATERIAL TO LOCK IT IN PLACE, USE SILICONE SPRAY LUBRICANT OR SIMILAR (long nose pliers or open end spanner can be used to push collar and tube onto the barb).



**FOR THERMOLITE COLLECTOR  
USE LOCKING COLLARS FOR ATTACHING COLLECTOR TO  
MANIFOLDS AND JOINING BARBS**

**DIRECTIONS:** STRIP BACK COLLECTOR BACKING (APPROX 40mm) AND SLIDE LOCKING COLLAR OVER TUBE. PUSH TUBE ON MANIFOLD BARBS OR SINGLE JOINING BARB (push tube on to about 2nd barb) AND SLIDE COLLAR OVER MATERIAL TO LOCK IT IN PLACE, USE SILICONE SPRAY LUBRICANT OR SIMILAR (long nose pliers or open end spanner can be used to push collar and tube onto the barb).

