


CUSTOM CONNECTOR KITS

HOW TO RELEASE TERMINALS WITH A WEATHER PACK REMOVAL TOOL



1 Disconnect the connector from its mate and release the folded down TPA lock from its position.



2 Center the tool's metal barrel around the now exposed terminal and press it into the open cavity until it stops.



3 Gently pull the wire from the back of the conenctor to release the terminal from its locked position. The tool can be removed from the cavity now.



