


Jacket Measurement Chart

Unit: CM

Size	Half Chest	Front Length	Full Shoulder	Back/Centre Lenght
S	55,5	XX	44	78,5
M	58	XX	45	80
L	60,5	XX	46	81,5
XL	63	XX	47	82,5
XXL	65,5	XX	48	83,5
XXXL	68	XX	49a	84,5

How To Take Measurements



- a. Half Chest**

Take the measurement at the largest point chest width passing the meter under the arms. To have your final Chest size, double the measure.
- b. Front Length**

Take the measurement from the base of the neck to the bottom of the garment.
- c. Full Shoulder**

Take the measurement left to right to have your shoulders size.
- d. CB Length**

Find center point of back between shoulders. Measure across to shoulder, then down.

Notes: To have your final Chest size, double your half size chest.