

SHADOWFOAM[®]

Follow these instructions carefully to ensure that you cut your foam safely, accurately and effectively.



Safety First



Cutting Shadow Foam requires you to use a sharp knife to cut the items into the foam. Please take extra care when using a knife.

This kit is intended for those over the age of 18.



- ✓ The Ultimate Customisable Foam
- ✓ UK Customer Support
- ✓ Online Video Tutorials

For more pictures of completed projects and other products that Shadow Foam have to offer, please visit our website:

www.shadowfoam.com

For any enquiries:

hello@shadowfoam.com

© Shadow Foam Ltd. 2023

SHADOWFOAM[®]



Cutting Instructions

Quick and Easy Organisation
Simply Cut & Peel

Things to remember...

Shadow Foam was designed to be the ultimate solution to create amazing custom foam liners. However, there are still things you have to consider to get a professional, high-quality finish.



Always use the forceps to attach and remove the blade to and from the handle, to avoid accidental cuts.



Make sure to replace the blades regularly. A dull blade can snag on the foam and create a jagged cut.



When creating your layout, leave at least 5mm between each item.



Always wear safety equipment. Our cutting kits include gloves, which should always be worn whilst cutting the foam.

Pro Cutting Kit Only...



If you make a mistake while cutting, you can use the repair glue to patch up any mis-cuts.



To achieve a smooth base, fit a foam spinner to an impact driver or drill. Slowly skim the surface of the foam, using light pressure while the spinner is rotating.

Cutting Instructions

Step One



If necessary, cut your foam down to the required size.

Create a layout of your tools by laying them on the top of the foam. You should leave at least 5mm between items.

Once you're happy with the layout, take a picture as a reference.

Step Two




Remove all of the tools except the one you're cutting first. We recommend starting in a corner.

Lightly press on the item, so it doesn't move. Trace cut around the item, keeping the knife perpendicular and as close to it as possible.

Once you meet the original cut mark, remove the item and cut again to the desired depth.

Step Three



Peel back layers until you reach the required depth. It is easier to pull from a point than a long edge.

If you are finding it difficult to peel then you may not have cut the profile deep enough.

The peeling of the foam is more of a 'ploughing' action. You need to follow the peel and dig your fingers through the foam as you follow the shape of the tool. The foam does not peel on the layers, it will peel below or above the layer line.

We would highly recommend watching our How-To videos before starting your project:

www.shadowfoam.com/how-to

Repeat

The process is the same for the rest of your items. Ensure that you keep checking the layout so you don't run out of room for all of your items.

Once you've finished, take a picture and share it with us!



Subscribe on YouTube!

We have plenty of 'How-to' videos on our YouTube channel, as well as weekly videos showcasing the uses of Shadow Foam. If you're looking for inspiration, or just a bit of fun, head over to our channel and check it out!

www.youtube.com/shadowfoam



Join the Foam Nation!

The best way to find new ideas and work out ways of tackling a challenge is to ask our community. Get the most out of your Shadow Foam by joining our Facebook group!

www.shadowfoam.com/join