



# **GUNGE MIXING INSTRUCTIONS:**

## **Step-by-Step Instructions For Mixing Your Gunge Powder:**

### **Prepare the necessary materials:**

- Gunge Powder
- Bucket (with a capacity of 10-12 liters)
- Warm water
- Immersion Blender (Optional)

1. Place the empty bucket in a suitable location where you can comfortably mix the Gunge.
2. Fill the bucket with 5 liters (small) of water. Make sure the water is warm but not scalding hot.
3. As you begin filling the bucket with water, start stirring the water using a mixing spoon or any other suitable tool. This will help create a consistent mixture.
4. While continuing to stir the water, slowly pour the Gunge Powder into the bucket. It is best to pour the powder in a steady stream while stirring simultaneously.
5. Keep stirring the mixture for approximately 5 minutes. This ensures that the powder fully dissolves and prevents any re-solidification at the bottom of the bucket.
6. Even if the powder appears to have dissolved before the 5-minute mark, it is recommended to continue stirring for the full duration to ensure a thorough mix.
7. After the 5-minute mixing process, set the bucket aside and let it sit for at least 10 minutes. This resting time allows the mixture to thicken and achieve the desired consistency.
8. For the best experience, it is recommended to let the bucket sit for an hour before using the Gunge. During this time, the Gunge will further solidify and become more suitable for use.

Remember to follow any additional instructions or precautions provided with your specific Gunge Powder product. Enjoy your Gunge experience!

If your Gunge Powder experiences re-solidification issues you can use an Immersion Blender to break up the clumps and have the perfect texture of Gunge.

