CARE AND MAINTENANCE RECOMMENDATIONS

Washing	Ironing	Tumbledry	Dry cleaning
Up to 60°C/140°F	On reverse only	Yes	Not recommen- ded

Storage life	Storage Temperature	Storage Lighting	Position
Up to 1 year	Dry room with 15-30°C/59°F-86°F	Away from sunlight	Vertical position

Care and maintenance:

- ✓ Always respect the garment instructions.
- ✓ Wait 24 hours after the application before the first wash.
- ✓ Avoid the use of aggressive products.

Washing recommendations:

- ✓ Respect the textile recommendations.
- ✓ Preferably inside out to extend the design's life.
- ✓ Do not bleach.

CARE AND MAINTENANCE RECOMMENDATIONS

820 Leopard

Washing	Ironing	Tumbledry	Dry cleaning
Up to 60°C/140°F	On reverse only	Yes	Not recommen- ded

Storage life	Storage Temperature	Storage Lighting	Position
Up to 1 year	Dry room with 15-30°C/59°F-86°F	Away from sunlight	Vertical position

Care and maintenance:

- ✓ Always respect the garment instructions.
- ✓ Wait 24 hours after the application before the first wash.
- ✓ Avoid the use of aggressive products.

Washing recommendations:

- ✓ Respect the textile recommendations.
- ✓ Preferably inside out to extend the design's life.
- ✓ Do not bleach.