

(717) 354-8998 • (877) 560-5966 New Holland, PA

#76 Round Side Table



Tools Required

- Hammer
- #2 Square Head Bit
- Power Drill
- 7/16" Socket or 7/16 wrench

Included Hardware

| Α | 1 | 4 | 1/4" x 31/2" Carriage Bolt |
|---|-------------|---|-------------------------------|
| В | | 4 | 1⁄4" Nut |
| С | | 8 | 1½" Screws |

Instructions:

- 1. Unpack items from box(es). Be sure to match any numbers & letters that you may find on the pieces.
- 2. Lay the table upside down and match the numbers and letters on the legs to the correct corner on the table. Fasten using 4 (A) 1/4" x 31/2" Carriage Bolts & 4 (B) 1/4" Nuts. (Illustration 2)
- Add the trim to the legs. Line up the marks on the legs and fasten using 4 (C)
 1½" Screws. Use 2 screws per leg.
 (Illustration 3) Repeat on the other side.





Illustration 2




Illustration 3