

HONDA Valkyrie GL1800C F6C

Parts list for MCS 6300 kit

<u>Item</u>	<u>Qty</u>	<u>Part Number</u>	<u>Description</u>
1	1	MCS 8000C	Computer
2	2		Velcro mounting tape (Computer mounting)
		<u>MCS 6302</u>	<u>Electric throttle servo assembly</u>
3	1	MCS 850	Throttle servo
4	1	MCS 850C	Servo nose
5	3		M4 x 12 pan head screws
6	1		3/4" x 3/32" (19 x 3mm) 'O' ring
7	1	MCS 850B	Cable sealing boot
8	1	MCS 6302A	Servo mounting bracket
9	2	HoseClamp6	Hose clamp 11~20mm
10	1	HoseClamp24	Hose clamp 27~51mm
		<u>MCS 6086</u>	<u>Throttle servo cable</u>
11	1	MCS 6086	Throttle servo cable
12	3	MCS 054	Wire ring cable retainer (1 spare)
13	1	MCS 003Z	6mm to 8mm adaptor
14	1		6mm flat washer
		<u>MCS 6085</u>	<u>Throttle servo cable spool/lost motion device</u>
15	1	MCS 6085	Throttle servo cable spool/lost motion device
		<u>MCS 6304</u>	<u>Control Switch assembly</u>
16	1	MCS 820-160	Control Switch
17	1	MCS 830B	Switch bracket (below handlebar clutch lever mount)
OR			
18	1	MCS 830X	Switch bracket (above handlebar clutch lever mount)
	4		4 gauge x 1/2" pan head self-tap screws
		<u>MCS 6301</u>	<u>Wiring harness</u>
19	1	MCS 6301	Wiring harness
a			Computer plug (26 pin)
b			Servo plug (4 pin)
c			Fuse holder (3 amp fuse)
d			Tach sensor connectors (yellow wire)
e1			Speed sensor connectors (blue/black wire)
e2			Sumitomo HX040 sealed connector
f			Clutch sensor (blue wire)
g			Power & brake sensor (orange and grey wires)
h			Ground connector (black wire)
i			Control switch plug (6 pin)
	1 bottle		Throttle cable oil
	10		150mm cable ties
	15		200mm cable ties
	4		300mm cable ties
	4cm		Double sided foam mounting tape (nut holder)
			Information, Set up and Operation Manual
			Operation and User Manual
			Installation Manual
			Trouble shooting guide

