

Counter Top

Worktop Oil is designed for untreated or previously oiled/sanded wood surfaces. The oil makes the surface highly water and dirt repellent. Use Worktop Oil, Natural, on both dark and light wood species – such as mahogany, merbau, teak, cherry, ash, oak, beech, maple, birch, pine etc. - to give the wood a mellow, golden color. Use Worktop Oil, White, to lighten up the wood or give it a whitewashed effect. Ensure good ventilation at all times during the application and drying time.

Products Needed

Worktop Oil Natural

WOCA Polishing Cloth

Worktop Oil White

White Polishing Pad



Buy Now!

Buy Now!

Buy Now!

Buy Now!

Instructions

1. If the surface is particularly smooth, sand it with 180 grit sandpaper.
2. Make sure the wood is dry and free of any dirt or grease. Clean the wood with Wood Cleaner. After cleaning, let the tabletop dry for at least 8 hours.
3. Stir the oil thoroughly before use.
4. Use a paintbrush to apply a suitable amount of oil in an even, adequate coat.
5. Wait approx. 20-30 minutes at 20°C (68°F) while the oil penetrates into the wood. If necessary, sand the wood while the surface is still wet with oil. Wet sand along with the wood grain with 320-400 grit sandpaper.
6. Next, wipe off all excess oil using a lint-free cotton cloth. Do not leave any excess oil on the surface.
7. Carefully polish the wood using a white polishing pad, which makes the surface more hard-wearing.

8. Repeat the treatment on highly absorbent surfaces.
9. The oil will thoroughly hardened after 24 hours at 20°C (68°F). Do not let the tabletop become wet during the hardening process.

Use Worktop Oil to maintain the tabletop four times a year, or as often as necessary. Before starting the maintenance procedure, clean the worktop using Wood Cleaner, and let the surface dry for at least 8 hours. Follow the procedure in items 2 through 7, but apply only one coat of oil.