




HYPERDRIVE® NEXT

10 Port Business Class USB-C® Dock



QUICK START GUIDE

READ BEFORE USE

To Enable Dual Monitor Use Follow These Easy Steps

STEP 1

Download the driver or application according to your OS platform (Window or macOS) from the website:



<http://www.siliconmotion.com/downloads/index.html>

STEP 2

Double click on InstantView App/Driver and follow the instructions to complete the installation.



STEP 3

For Windows

Check “Always Trust Software from Silicon Motion, Inc” and click install.

For macOS

Make sure to allow permissions to record screen in the Security Settings.

STEP 4

Connect the Hyper USB-C Dock to the computer and enjoy the content display on the screen.

STEP 5

To further customize your experience go into the Display Settings on your mac or pc.

If you need further assistance, reach out to our customer support team at:
support@hypershops.com or call **844-674-6789**