


SPARE PARTS EXPLODED VIEW for model: PMG-- - 01122022


● 11099 / ○ 11100



11097
Cable: 11096
Fuse (10pcs): 11095

fixed power cable


● 11182 / ○ 11183
(incl. power cable, fittings, 11096, 11097, 11098 & 2pcs fuse)



11098


detachable power cable

● 11101 / ○ 11102
(incl. fittings, 11036 & 2pcs fuse)




11036
Fuse (10pcs): 11095


11037
(Greg)



11038
(EPIC Greg)



Screw position for 11037
for 11038



11089 (230V - LRS)
11090 (110V - IRM)

11080 (4pcs) standard
(11081 (4pcs) high feet)

11179
Cable: 11093

10405 (230V - LRS)
11162 (110V - IRM)

10389 (5pcs)
Cable: 11084

11068

11074

11069

10428

10424
Cable: 11092 (230V - LRS)
11161 (110V - IRM)

10427


11085
Cable: 11086

11108

10431

11179

Cable: 11093



11105

Nozzle + O-ring (5pcs): 10508
O-ring (10pcs): 10510

Cone piece (10pcs): 11071

10401

Cable: 11088

Cover (10pcs): 11075

11072

11106

Cable: 11087

10418
Cap (10pcs): 11077



**PERFECT
MOOSE**

help.perfectmoose.com
help@perfectmoose.com
0032 52 49 90 79