# **INSTALLATION GUIDE** SUBARU EQUAL LENGTH HEADER



# TOOLS REQUIRED:

10mm Socket 12mm Socket 14mm Socket O2 Sensor Socket socket 3/8 Ratchet

### WHAT'S IN THE BOX: 1x MAP EJ25 Header

# 1. RAISE VEHICLE AND REMOVE Lower Splash guard



# 2. REMOVE HEAT SHIELDS COVERING THE EXHAUST MANIFOLD STUDS AND REMOVE GROUND STRAP





### **2. CONTINUED**

### 3. DISCONNECT 02 SENSOR AND REMOVE THE SENSOR FROM THE FACTORY EXHAUST MANIFOLD







4. REMOVE 2 BOLTS SECURING FACTORY Manifold to your up-pipe 5. REMOVE 6 14MM NUTS SECURING FACTORY MANIFOLD







# 6. REMOVE FACTORY MANIFOLD From the vehicle



# 7. INSTALL YOUR NEW MAP ELH WITH THE SUPPORT BRACKET IN PLACE



8. INSTALL 2 BOLTS SECURING MAP ELH TO THE UP PIPE



# **8. CONTINUED** MUST DO IN THIS ORDER TO ENSURE The support bracket will seat correctly



11. RELOCATE GROUND STRAP ONTO VALVE COVERS

### 9. REINSTALL 6 14MM NUTS SECURING MAP ELH TO THE ENGINE



### **12. START UP AND CHECK FOR LEAKS**

### 10. INSTALL 02 SENSOR INTO YOUR MAP ELH



# **13. REINSTALL SPLASH SHIELD**





### THANK YOU FOR CHOOSING MAPERFORMANCE!

If you have any problems or concerns during installation of this product, feel free to call or email us:

#### 1-888-MAPERFORMANCE

sales@maperformance.com Show us some photos! @maperformance / #maperformance