


# GRAB

VERIFY WITH TAPE MEASUREMENTS

This curve should match  
the round hole in subframe

A diagram illustrating a fit check. Two grey circles are positioned vertically. A dashed line with an arrow at its right end points to a curve that fits between the two circles. A large black arrow on the right side of the page points towards the diagram.