

**ODMB Detector Motherboard Parts List**  
(in order of recommended assembly)

<b>Qty.</b>	<b>Symbol</b>	<b>Description</b>
27	—	4-40 x 1/4 Pan-head machine screws (Digi-Key H142)
27	—	4-40 Hex nuts (Digi-Key H216) (soldered to underside of board)
12	S1-S12	5-pin Waldom straight-headers (Mouser 538-26-60-2050 or use breakaway section of Mouser 538-26-48-1241 per text)

Author's recommendation for supplier given in parentheses above with part numbers where applicable. Equivalent parts may be substituted.