SECO-LARM®

Access

SIGNALING

Ų

1,200-lb Electromagnetic Locks

E-941SA-1200 UL Listed (294,1034, 864,10C*) E-941SA-1K2PQ with bond sensor, status LED UL listed (10C[†]) E-941SA-1K2PD with bond sensor, status LED, Timer

Features:

- 1,200-lb Holding force •
- Selectable 12/24 VDC operation •
- Anodized aluminum housing (US 28) •
- No residual magnetism •
- MOV surge protection •
- Adjustable mounting bracket •
- Complete mounting hardware for typical installations •
- "L" and "Z" brackets available for easy mounting •
- Detachable faceplate

E-941SA-1K2PQ Only:

- Built-in dual-colored status LED and bond sensor to indicate locking status
- Bond sensor relay rated 3A@12VDC

E-941SA-1K2PD Only:

- Built-in dual-colored status LED and bond sensor to • indicate locking status
- Built-in timer: 1~78 seconds

Specifications:

| Model | | E-941SA-1200 | E-941SA-1K2PQ | E-941SA-1K2PD |
|--------------------------|-------|-------------------------|---------------|---------------|
| Holding force | | 1,200-lb (545kg) | | |
| Operating voltage | | 12/24 VDC±10% | | |
| Current draw | 12VDC | 500mA@12VDC | | |
| | 24VDC | 250mA@24VDC | | |
| Bond sensor relay | | | 3A@12VDC | |
| Operating temperature | | 14°~131° F (-10°~55° C) | | |
| Weight | | 11-lb (5kg) | | |
| Bond sensor relay | | | ✓ | ✓ |
| Status LED | | | ✓ | \checkmark |
| Built-in timer | | | | \checkmark |

*The E-941SA-1200 is UL 294, UL 1034, and UL 864 for USA, UL 10C for USA and Canada [†]The E-941SA-1K2PQ is UL 10C for the USA and Canada.


SECO-LARM® U.S.A., Inc.

16842 Millikan Avenue, Irvine, CA 92606 Phone: (949) 261-2999 | (800) 662-0800 Fax: (949) 261-7326 Website: www.seco-larm.com Email: sales@seco-larm.com





1/4" (6mm) 25/8" (67mm) 101/2" (268mm) 15/8" (42mm) Armature Plate



Additional brackets for easy mounting:



Copyright © 2020 SECO-LARM U.S.A, Inc. All rights reserved. All trademarks are the property of SECO-LARM U.S.A., Inc. or their respective owners. The SECO-LARM policy is one of continual development. For that reason, SECO-LARM reserves the right to change prices and specifications without notice. SECO-LARM is not responsible for misprints.

PI_E-941SA-1200_201021.docx