

Application Guide

| ACURA | | FRONT | | | | REAR | | | |
|--------------------------------|-------|------------------------|-----------------------|----------------------|---------------------------|------------------------|-----------------------|----------------------|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| Integra | 90-93 | AP409 | RC409 | 0409 | HB242.661 | AP374 | RC374 | | HB350.496 |
| Integra | 94-01 | AP617 | RC617 | | HB245.631 | AP374 | RC374 | | HB350.496 |
| Integra Type R | 97-01 | AP503 | RC503 | 0503 | HB143.680 | AP374 | RC374 | | HB350.496 |
| NSX | 91-05 | AP503 | RC503 | 0503 | HB143.680 | AP504 | RC504 | | HB185.590 |
| NSX | 17-21 | AP2253 | | | | AP2254 | | | |
| RSX | 02-06 | AP621 | RC621 | | HB418.646 | AP365 | R537 | 0537 | HB145.570 |
| RSX Type S | 02-06 | AP829 | RC829 | | HB361.622 | AP365 | R537 | 0537 | HB145.570 |

| AUDI | | FRONT | | | | REAR | | | |
|----------------------|-------|--------------------------|--------------------------|-----|---------------------------|--------------------------|-------------------------|-----|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| R8 | 08-20 | AP1029 | R1029 | | HB609.572 | AP1155 | R780.18 | | HB193.670 |
| RS5 | 18-19 | AP1894 | | | | AP1898 | | | HB866.652 |
| RS7 | 14-18 | AP1291 | R1291.16 | | HB731.620 | AP1547 | RC1547 | | HB823.652 |
| TT | 16-21 | AP1760 | | | HB788.745 | AP1761 | RC1761 | | HB789.600 |
| TTS | 16-20 | AP1876 | | | | AP1761 | RC1761 | | HB789.600 |
| TTRS | 16-19 | AP1029.2 | | | HB609.572 | AP1761.1 | RC1761 | | HB789.600 |

| ALFA ROMEO | | FRONT | | | | REAR | | | |
|---|-------|--------------------------|-------------------------|----------------------|---------------------------|--------------------------|------------------------|-----|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| 1600 Spider, GTV, Guilia | 64-68 | AP31 | R31.15 | | HB172.595 | AP30 | RC30 | | HB713.585 |
| 1750,2000,Berlina, GTV, Spider | 68-95 | AP45 | R45.15 | | HB171.590 | AP30 | RC30 | | HB713.585 |
| 2000 Spider, Veloce, Graduate | 75-95 | AP45 | R45.15 | | HB171.590 | AP30 | RC30 | | HB713.585 |
| Alfetta, Sport Sedan, Sprint Veloce | 75-80 | AP31 | R31.15 | | HB172.595 | AP30 | RC30 | | HB713.585 |
| Alfetta GT, GTV | 75-80 | AP31 | R31.15 | | HB172.595 | AP30 | RC30 | | HB713.585 |
| GTV V6 | 80-86 | AP174 | RC174 | 0109 | HB180.640 | AP30 | RC30 | | HB713.585 |
| Milano | 86-89 | AP174 | RC174 | 0109 | HB180.640 | AP30 | RC30 | | HB713.585 |
| 4C | 15-20 | AP1379.1 | R593.14 | | HB548.590 | AP1822 | RC1822 | | |
| Giulia | 17-21 | AP2052 | | | | AP1989.1 | | | |
| Giulia Quadrifoglio | 17-21 | AP1116 | RC1116 | | | AP2043 | | | |

| BMW | | FRONT | | | | REAR | | | |
|--------------------------------|---------|--------------------------|------------------------|----------------------|---------------------------|-------------------------|------------------------|----------------------|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| M3 E30 | 87-91 | AP395 | RC395 | 0395 | HB137.690 | AP396 | RC396 | 0396 | HB227.630 |
| M3 E36 | 95-99 | AP394 | R394 | 0394 | HB135.770 | AP396 | RC396 | 0396 | HB227.630 |
| M3 E46 | 01-07 | AP394 | R394 | 0394 | HB135.770 | AP683 | RC683 | 0548 | HB518.642 |
| M3 E90,92,93 | 08-13 | AP918 | RC918 | 0918 | HB551.748 | AP919 | RC919 | 0919 | HB630.626 |
| M3 F80 | 14-18 | AP1609 | RC1609 | 1609 | HB765.664 | AP1656 | RC1656 | 1656 | HB766.624 |
| M2 | 16-18 | AP1609 | RC1609 | 1609 | HB765.664 | AP1656 | RC1656 | 1656 | HB766.624 |
| M4 | 15-20 | AP1609 | RC1609 | 1609 | HB765.664 | AP1656 | RC1656 | 1656 | HB766.624 |
| M5 | 18-20 | AP2155 | | | | AP2059 | | | |
| M235i, iX | 14-16 | AP1609 | RC1609 | 1609 | HB765.664 | AP1656 | RC1656 | 1656 | HB766.624 |
| 1 Series M | 11-12 | AP918 | RC918 | 0918 | HB551.748 | AP919 | RC919 | 0919 | HB630.626 |
| 128i | 08-13 | AP1061.1 | | | HB534.750 | AP1267 | | | HB621.638 |
| 135i | 08-13 | AP1371 | RC1371 | | HB603.616 | AP1372 | RC1372 | | HB604.598 |
| 228 | 14-16 | AP1561 | | | HB748.723 | AP1613 | | | HB749.648 |
| 228 w/340 disc | 14-16 | AP1609 | RC1609 | 1609 | HB765.664 | AP1656 | RC1656 | 1656 | HB766.624 |
| 325,328 E30 | 84-4/91 | AP278 | RC278 | 0278 | HB195.640 | AP279 | RC279 | 0279 | HB399.630 |
| 325,328 E36 | 4/94-00 | AP558 | RC558 | 0558 | HB136.690 | AP396 | RC396 | 0396 | HB227.630 |
| 325 E46 | 01-07 | AP558 | RC558 | 0558 | HB136.690 | AP396 | RC396 | 0396 | HB227.630 |
| 330 M Sport | 16-18 | AP1609 | RC1609 | 1609 | HB765.664 | AP1656 | RC1656 | 1656 | HB766.624 |
| 2002 | 69-76 | AP32 | | | | SHOE459 | | | |
| 2002 Tii | 74-76 | AP82 | | 0082 | HB206.565 | SHOE459 | | | |

| ASTON MARTIN | | FRONT | | | | REAR | | | |
|--------------------------------|-------|------------------------|-----------------------|----------------------|---------------------------|------------------------|-----------------------|----------------------|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| DB9 | 05-14 | AP1165 | R1001 | 7781 | HB683.651 | AP1166 | | | |
| DB11 | 16-19 | AP1990 | | | | AP1165 | | | |
| Vanquish V12 | 01-05 | APF-40 | R780 | | HB193.670 | AP1166 | | | |
| Vanquish S | 01-05 | CP7040 | R921 | 7838 | HB586.660 | AP1598 | | | HB585.660 |
| Vantage V8 | 05-12 | AP1165 | R1001 | 7781 | HB683.651 | AP1166 | | | |
| Vantage V8/V8S | 12-18 | AP1990 | | | | AP1166 | | | |
| Rapide | 11-18 | AP1990 | | | | AP1165 | R1001 | 7781 | HB683.651 |

| CADILLAC | | FRONT | | | | REAR | | | |
|-----------------------|-------|------------------------|------------------------|-----|---------------------------|-------------------------|-------------------------|-----|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| CT6-V | 19-20 | AP2274 | | | | AP2303 | | | |
| CTS-V | 09-15 | AP1405 | RC1405 | | HB649.605 | AP592.1 | R592.15 | | HB194.570 |
| CTS-V | 16-19 | AP1835 | RC1835 | | HB843.604 | AP592.1 | R592.15 | | HB194.570 |

***This is a sampling of the more popular models if your vehicle isn't listed
[Click here](#) to search our site*** ALL Listings are for NON Ceramic discs

Application Guide

| CHEVROLET | | FRONT | | | | REAR | | | | FERRARI | | FRONT | | | | REAR | | | |
|---|-------|------------------------|------------------------|----------------------|---------------------------|--------------------------|-------------------------|----------------------|---------------------------|----------------------------------|-------|---------------------------|------------------------|----------------------|---------------------------|---------------------------|-----------------------|----------------------|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk | Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| Camaro | 98-02 | AP749 | RC749 | | HB249.575 | AP750 | RC750 | | HB250.653 | 250 | 59-64 | DD705 | DD705 | | | DD704 | DD704 | | |
| Camaro 1LE | All | AP412 | R412 | 0412 | HB111.610 | AP413 | R413 | 0413 | HB112.540 | 275, 330 | 64-66 | DD705 | DD705 | | | DD704 | DD704 | | |
| Camaro V6 | 10-15 | AP1404 | RC1404 | | HB638.702 | AP1337 | RC1337 | | HB639.645 | 275, 330 | 67-68 | GD522 | GD522 | | HB244.624 | GD557 | GD557 | | |
| Camaro V8 | 10-15 | AP1474 | R1001 | 7781 | HB726.582 | AP592.1 | R592.15 | | HB194.570 | 308,GT4,GTB,GTQV | 74-85 | AP45 | R45.15 | | HB171.590 | AP31 | R31 | | HB172.595 |
| Camaro ZL1 | 12-15 | AP1405 | RC1405 | | HB649.605 | AP592.1 | R592.15 | | HB194.570 | 328,GTB,GTS | 85-88 | AP395 | RC395 | 0395 | HB137.690 | FRP206 | | | |
| Camaro Z28 | 2015 | AP1395 | | | HB631.622 | AP1165 | | | HB683.651 | 330 GTC/GTS | 66-68 | FRP104 | | | | GD557 | GD557 | | |
| Camaro4pistJL55 | 16-21 | AP1001 | R1001 | 7781 | HB453.585 | AP1914 | | | | 348 GTB,GTS | 89-95 | AP345 | R608 | 0345 | HB170.650 | AP345 | R608 | 0345 | HB170.650 |
| Camaro SS 4pist | 16-21 | AP1474 | R1001 | 7781 | HB726.582 | AP1718 | RC1718 | | HB727.592 | 355 Berlinetta | 94-99 | AP345 | R608 | 0345 | HB170.650 | AP345 | R608 | 0345 | HB170.650 |
| Camaro SS 6pist | 16-21 | AP1405 | RC1405 | | HB649.605 | AP1718 | RC1718 | | HB727.592 | 355 Challenge | 95-00 | FRP302.16 | R2000 | 7700 | HB105.620 | FRP302.16 | R2000 | 7700 | HB105.620 |
| Camaro ZL1 | 16-21 | AP1835 | RC1835 | | HB843.604 | AP592.1 | R592.15 | | HB194.570 | 360 Modena | 00-04 | AP1166 | | | | AP592.1 | R592 | | HB194.570 |
| Corvette Dual Pin | 63-82 | AP8882 | RC8882 | | HB128.505 | AP8882 | RC8882 | | HB128.505 | 365w/RrGirling | 67-68 | GD522 | GD522 | | HB244.624 | GD557 | GD557 | | |
| Corvette Single Pin | 63-82 | APD-8 | R8.13 | 0008 | HB126.505 | APD-8 | R8.13 | 0008 | HB126.505 | 365 GTB/GTC | 67-76 | FRP104 | | | | GD557 | GD557 | | |
| Corvette | 84-87 | AP294 | | | HB173.570 | AP413 | R413 | 0413 | HB112.540 | 365 w/ATE Cal | 68-75 | AP82 | RC82 | 0082 | HB206.565 | AP32 | RC32 | | |
| Corvette | 88-96 | AP412 | R412 | 0412 | HB111.610 | AP413 | R413 | 0413 | HB112.540 | 430 | 06-09 | AP1166 | | | | AP592.15 | R592 | | HB194.570 |
| Corvette | 97-13 | AP731 | R731 | 0731 | HB247.575 | AP732 | R732 | 0732 | HB248.650 | 456GT | 94-96 | AP639 | R639 | | HB181.660 | AP345 | R608 | 0345 | HB170.650 |
| Corvette Z06, Grand Sport | 06-13 | AP1185 | R1185 | | HB658.570 | AP1185.1 | R1185 | | HB659.570 | 512 TR | 92-96 | AP639 | R639 | | HB181.660 | AP345 | R608 | 0345 | HB170.650 |
| Corvette Stingray | 14-19 | AP1001 | R1001 | 7781 | HB453.585 | AP1718 | RC1718 | | HB727.592 | 550 Maranello | 96-02 | AP639 | R639 | | HB181.660 | AP345 | R608 | 0345 | HB170.650 |
| Corvette Z06, Grand Sport | 14-19 | AP1405 | RC1405 | | HB649.605 | AP1718 | RC1718 | | HB727.592 | 575 Maranello | 03-04 | AP1133 | R639 | | HB181.660 | AP345 | R608 | 0345 | HB170.650 |
| Corvette Base | 20-21 | AP2251 | | | HB924.565 | AP2369 | | | HB925.597 | 599 GTB Fior | 06-12 | AP1395 | | | HB631.622 | AP1165 | | | HB683.651 |
| Corvette Z51 | 20-21 | AP2312 | | | HB926.577 | AP2366 | | | HB927.568 | 612 Scaglietti | 04-09 | AP1165 | | | HB683.651 | AP1166 | | | |
| | | | | | | | | | | Berlinetta Boxer | 73-84 | AP82 | RC82 | 0082 | HB206.565 | AP32 | RC32 | | |
| | | | | | | | | | | F-40/F50 | 88-97 | APF-40 | R780 | | HB193.670 | APF-40 | R780 | | HB193.670 |
| | | | | | | | | | | Testarossa, GTO | 85-91 | AP82 | RC82 | 0082 | HB206.565 | AP32 | RC32 | | |

| DODGE | | FRONT | | | | REAR | | | |
|--|-------|------------------------|------------------------|----------------------|---------------------------|-------------------------|----------------------|----------------------|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| Challenger R/T | 09-11 | AP1058 | | 1058 | HB509.678 | AP1057 | | 1057 | HB508.675 |
| Challenger SRT-8 | 08-20 | AP1149 | RC1149 | | HB563.656 | AP592.1 | R592 | | HB194.570 |
| Challenger Perf Brakes | 12-19 | AP1058 | | 1058 | HB509.678 | AP1057 | | 1057 | HB508.675 |
| Challenger Hellcat | 13-20 | AP1405 | RC1405 | | HB649.605 | AP592.1 | R592 | | HB194.570 |
| Charger Hellcat | 13-20 | AP1405 | RC1405 | | HB649.605 | AP592.1 | R592 | | HB194.570 |
| Charger SRT-8/ Super Bee | 06-17 | AP1149 | RC1149 | | HB563.656 | AP592.1 | R592 | | HB194.570 |

| FIAT | | FRONT | | | | REAR | | | |
|---------------------------------|-------|--------------------------|-------------------------|-----|---------------------------|------------------------|------------------------|-----|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| 124 | 65-67 | AP54 | | | | AP71 | | | |
| 124 | 68-82 | AP54.1 | | | | AP71 | | | |
| X 1/9, Bertone | 74-88 | AP54.1 | | | | AP71 | | | |
| Spider w/Brembo | 18-20 | AP1379.2 | R593.14 | | HB548.590 | AP1180 | RC1180 | | HB523.539 |
| Spider | 17-20 | AP1903 | RC1903 | | HB898.572 | AP1180 | RC1180 | | HB523.539 |

Application Guide

| FORD | | FRONT | | | | REAR | | | | HONDA | | FRONT | | | | REAR | | | |
|--|-------|------------------------|------------------------|----------------------|---------------------------|-------------------------|-------------------------|----------------------|---------------------------|--|-------|------------------------|-----------------------|----------------------|---------------------------|-------------------------|-----------------------|----------------------|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk | Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| Mustang | 65-67 | APD-11 | RCD-11 | | HB471.510 | SHOE | | | | Civic Coupe DX M/T | 93-95 | AP273 | RC273 | | HB218.583 | SHOE546 | | | |
| Mustang W/ Lincoln Cal | 65-67 | APD-1 | RCD-1 | | | APD-102 | | | | Civic Cp EX w/ABS | 93-95 | AP617 | RC617 | | HB245.631 | AP374 | RC374 | | HB350.496 |
| Mustang | 68-73 | APD-34 | | | HB646.526 | SHOE | | | | Civic Coupe DX,HX | 96-00 | AP273 | RC273 | | HB218.583 | SHOE517 | | | |
| Mustang | 74-78 | APD-90 | | | | SHOE | | | | Civic Coupe EX | 96-00 | AP764 | RC764 | 0465 | HB275.620 | SHOE517 | | | |
| Mustang | 83-86 | AP310 | | 0310 | HB263.650 | SHOE569 | | | | Civic Coupe | 01-05 | AP764 | RC764 | 0465 | HB275.620 | SHOE517 | | | |
| Mustang SVO | 84-86 | AP200 | | | HB125.650 | APD-204 | | | | Civic Coupe Si | 99-00 | AP764 | RC764 | 0465 | HB275.620 | AP374 | RC374 | | HB350.496 |
| Mustang 4cyl | 87-93 | AP310 | | 0310 | HB263.650 | SHOE569 | | | | Civic Coupe DX, LX | 06-11 | AP764 | RC764 | 0465 | HB275.620 | SHOE913 | | | |
| Mustang V8 | 87-93 | AP431 | | | HB263.650 | SHOE569 | | | | Civic Coupe EX | 06-11 | AP764 | RC764 | 0465 | HB275.620 | AP365 | RC365 | 0537 | HB145.570 |
| Mustang Cobra | 1993 | AP431 | | | HB263.650 | AP347 | RC347 | | HB580.627 | Civic Coupe Si | 06-11 | AP829 | RC829 | | HB361.622 | AP365 | RC365 | 0537 | HB145.570 |
| Mustang | 94-98 | AP600 | RC600 | | HB182.660 | AP627 | RC627 | 0627 | HB183.660 | Civic Coupe EX | 13-15 | AP914 | RC914 | | HB393.665 | AP365 | RC365 | 0537 | HB145.570 |
| Mustang Cobra | 94-04 | AP412 | R412 | 0412 | HB111.610 | AP627.1 | R627.15 | 0627 | HB183.585 | Civic Coupe Si | 12-15 | AP914 | RC914 | | HB393.665 | AP365 | RC365 | 0537 | HB145.570 |
| Mustang | 99-04 | AP804 | RC804 | 0804 | HB274.610 | AP627 | RC627 | 0627 | HB183.660 | Civic Coupe | 16-18 | AP914 | RC914 | | HB393.665 | AP1878 | | | HB900.572 |
| Mustang GT & V6 | 05-10 | AP1081 | RC1081 | 1081 | HB484.670 | AP1082 | RC1082 | 1082 | HB485.656 | Civic Sedan Si | 18-19 | AP1697 | | | HB875.666 | AP1878 | | | HB900.572 |
| Mustang Shelby | 07-11 | AP1001 | R1001 | 7781 | HB453.585 | AP1082 | RC1082 | 1082 | HB485.656 | Civic Hatchback | 88-91 | AP273 | RC273 | | HB218.583 | SHOE546 | | | |
| Mustang V6 & V8 | 11-14 | AP1463 | RC1081 | 1081 | HB484.670 | AP1465 | RC1082 | 1082 | HB485.656 | Civic Hatchback 1500 | 92-95 | AP273 | RC273 | | HB218.583 | SHOE546 | | | |
| Mustang w/ Brembo/Boss 302 | 11-14 | AP1001 | R1001 | 7781 | HB453.585 | AP1465 | RC1082 | 1082 | HB485.656 | Civic Hatchback 1600 w/o ABS | 93-95 | AP273 | RC273 | | HB218.583 | AP374 | RC374 | | HB350.496 |
| Mustang Shelby | 11-12 | AP1001 | R1001 | 7781 | HB453.585 | AP1465 | RC1082 | 1082 | HB485.656 | Civic Hatchback 1600 w/ABS | 93-95 | AP617 | RC617 | | HB245.631 | AP374 | RC374 | | HB350.496 |
| Mustang Shelby | 13-14 | AP1666 | RC1666 | | HB616.607 | AP1465 | RC1082 | 1082 | HB485.656 | Civic Hatchback | 96-00 | AP273 | RC273 | | HB218.583 | SHOE517 | | | |
| Mustang Shelby GT350 | 15-20 | AP1853 | RC1853 | | HB903.604 | AP1854 | RC1854 | | HB904.630 | Civic Hatchback Si | 02-03 | AP764 | RC764 | 0465 | HB275.620 | AP365 | RC365 | 0537 | HB145.570 |
| Mustang GT W/Brembo | 15-21 | AP1792 | RC1792 | | HB805.615 | AP1793 | RC1793 | | HB774.650 | Civic Hatchback Si | 04-05 | AP621 | RC621 | | HB418.646 | AP365 | RC365 | 0537 | HB145.570 |
| Mustang GT | 15-21 | AP1784 | RC1784 | | HB802.661 | AP1793 | RC1793 | | HB774.650 | Civic Hatchback | 17-18 | AP914 | RC914 | | HB393.665 | AP1878 | | | HB900.572 |
| Fiesta R/Disc | 14-17 | AP1730 | RC1730 | | HB725.650 | AP886 | RC886 | | HB430.547 | Civic Type R | 18-21 | AP1001 | R1001 | 7781 | HB453.585 | AP1878 | | | HB900.572 |
| Focus RS | 16-18 | AP1977 | | | HB889.550 | AP1095 | RC1095 | | HB478.605 | CRX1500,1600 DX | 84-87 | AP256 | RC256 | | HB397.585 | SHOE546 | | | |
| Focus ST | 13-18 | AP1645 | | | HB519.682 | AP1095 | RC1095 | | HB478.605 | CRX 1500DX | 88-91 | AP273 | RC273 | | HB218.583 | SHOE546 | | | |
| GT | 05-06 | AP1001 | R1001 | 7781 | HB453.585 | AP1001 | R1001 | 7781 | HB453.585 | CRX 1500HF | 88-91 | AP256 | RC256 | | HB397.585 | SHOE546 | | | |
| | | | | | | | | | | CRX 1500,1600 Si | 88-89 | AP273 | RC273 | | HB218.583 | SHOE546 | | | |
| | | | | | | | | | | CRX 1500,1600 Si | 90-91 | AP373 | RC373 | | HB113.590 | AP374 | RC374 | | HB350.496 |
| | | | | | | | | | | CR-Z | 11-15 | AP1394 | | | HB418.646 | AP365 | RC365 | 0537 | HB145.570 |
| | | | | | | | | | | CR-Z | 2016 | AP914 | RC914 | | HB393.665 | AP1841 | | | |
| | | | | | | | | | | S2000 | 00-09 | AP829 | RC829 | | HB361.622 | AP365 | RC365 | 0537 | HB145.570 |

***This is a sampling of the more popular models if your vehicle isn't listed
[Click here](#) to search our site*** ALL Listings are for NON Ceramic discs

Application Guide

| HYUNDAI | | FRONT | | | | REAR | | | |
|--------------------------------|-------|------------------------|-----|-----|---------------------------|------------------------|-----|-----|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| Veloster | 15-21 | AP1828 | | | | AP1813 | | | HB734.584 |
| Veloster Turbo | 12-17 | AP1675 | | | HB661.667 | AP1813 | | | HB734.584 |
| Veloster Turbo | 19-21 | AP1855 | | | | AP1813 | | | HB734.584 |
| Veloster N | 19-21 | AP2211 | | | | AP2212 | | | |

| JAGUAR | | FRONT | | | | REAR | | | |
|------------------------------------|-------|------------------------|-----|-----|---------------------------|------------------------|-----|-----|------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| F-Type S (Iron) | 14-18 | AP1750 | | | | AP1752 | | | |
| F-Type R,V8S(Iron) | 14-19 | AP1750 | | | | AP1753 | | | |
| F-Pace SVR | 19-20 | AP2257 | | | | AP2367 | | | |
| XKR(S) w/Alcon | 10-15 | AP1355 | | | HB760.620 | AP1356 | | | |
| XKR-S GT | 14-15 | AP1763 | | | | AP1764 | | | |

| KIA | | FRONT | | | | REAR | | | |
|------------------------------------|-------|------------------------|-----|-----|------|--------------------------|-----|-----|------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| Stinger Non/Brembo | 18-21 | AP2117 | | | | AP1816.1 | | | |
| Stinger w/Brembos | 18-21 | AP2145 | | | | AP2144 | | | |

| LEXUS | | FRONT | | | | REAR | | | |
|-----------------------------|-------|------------------------|------------------------|-----|---------------------------|--------------------------|------------------------|-----|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| GS F | 16-19 | AP1440 | | | | AP1807 | | | |
| IS F | 08-14 | AP1365 | RC1365 | | HB616.607 | AP1366 | RC1366 | | HB722.652 |
| IS200 Turbo | 16-17 | AP1118 | | | HB812.680 | AP1391.1 | | | HB799.597 |
| RC F | 15-21 | AP1440 | | | | AP1807 | | | |
| IS300 | 16-20 | AP1118 | | | HB812.680 | AP1391.1 | | | HB799.597 |
| IS350 | 09-13 | AP1118 | | | HB812.680 | AP1113 | | | HB562.612 |
| IS350 | 14-20 | AP1118 | | | HB812.680 | AP1391.1 | | | HB799.597 |

| LOTUS | | FRONT | | | | REAR | | | |
|----------------------------|-------|-------------------------|-------------------------|----------------------|---------------------------|-------------------------|-------------------------|----------------------|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| Elise | 05-11 | AP109 | RC109 | 0109 | HB180.560 | AP491.1 | R491.12 | 0491 | HB278.465 |
| Evora | 10-16 | AP1598 | RC1598 | 7869 | HB585.660 | AP1599 | RC1599 | 7870 | |
| Exige | 05-11 | AP109 | RC109 | 0109 | HB180.560 | AP491.1 | R491.12 | 0491 | HB278.465 |
| Exige S240 | 08-09 | CP7600 | CP7600 | | HB587.630 | AP491.1 | R491.12 | 0491 | HB278.465 |
| Esprit | 95-04 | AP592.1 | R592.15 | | HB194.570 | AP491.1 | R491.12 | 0491 | HB278.465 |

| MASERATI | | FRONT | | | | REAR | | | |
|---------------------------------|-------|------------------------|------------------------|-----|---------------------------|------------------------|-----|-----|------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| Quattroporte V6 | 14-20 | AP1116 | RC1116 | | HB616.607 | AP1270 | | | |
| Quattroporte V8 | 14-20 | AP1990 | | | | AP1270 | | | |
| GranSport | 2012 | AP1116 | RC1116 | | HB616.607 | AP1166 | | | |
| GranTurismo | 13-17 | AP1116 | RC1116 | | HB616.607 | AP1166 | | | |
| GranTurismo | 09-11 | AP1133 | R639 | | HB181.660 | AP1166 | | | |

| MAZDA | | FRONT | | | | REAR | | | |
|----------------------------------|-------|--------------------------|-------------------------|----------------------|---------------------------|------------------------|------------------------|----------------------|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| Miata | 89-93 | AP457 | R525 | | HB148.560 | AP458 | RC458 | | HB157.484 |
| Miata | 94-05 | AP635 | R635 | 0635 | HB149.505 | AP636 | RC636 | 0636 | HB159.492 |
| Miata Sport Susp | 01-05 | AP890 | RC890 | | HB431.606 | AP891 | RC891 | | HB442.496 |
| Miata | 06-15 | AP1179 | RC1179 | | HB522.565 | AP1180 | RC1180 | | HB523.539 |
| Miata MX-5 | 16-21 | AP1903 | RC1903 | | HB898.572 | AP1180 | RC1180 | | HB523.539 |
| Miata Brembo | 16-21 | AP1379.2 | R593.14 | | HB548.590 | AP1180 | RC1180 | | HB523.539 |
| RX-7 12a | 79-85 | AP76 | R76 | | HB150.555 | AP235 | RC235 | | HB151.505 |
| RX-7 4Lug | 84-88 | AP131 | RC131 | | HB152.540 | AP332 | RC332 | | HB158.515 |
| RX-7 5lug/ Turbo | 86-88 | AP331 | RC331 | | HB155.580 | AP332 | RC332 | | HB158.515 |
| RX-7 Solid Disc | 89-92 | AP131 | RC131 | | HB152.540 | AP332 | RC332 | | HB158.515 |
| RX-7 Vented | 89-92 | AP331 | RC331 | | HB155.580 | AP332 | RC332 | | HB158.515 |
| RX-8 | 04-11 | AP1009 | RC1009 | | HB470.643 | AP1008 | RC1008 | | HB378.565 |
| 3 Mazdaspeed | 10-13 | AP915.2 | RC915 | | HB515.760 | AP1095 | RC1095 | | HB478.605 |
| 6 | 16-17 | AP1711 | | | | AP1874 | | | |

| MERCEDES BENZ | | FRONT | | | | REAR | | | |
|--------------------------------------|-------|------------------------|-----------------------|-----|---------------------------|------------------------|------------------------|-----|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| AMG GT/S Silver Cal | 16-17 | AP1873 | | | | AP1669 | RC1669 | | HB830.667 |
| AMG GT/S Red Cal | 16-17 | AP1291 | R1291 | | HB731.620 | AP1669 | RC1669 | | HB830.667 |
| C63 AMG | 08-13 | AP1291 | R1291 | | HB731.620 | AP1373 | RC1373 | | HB846.534 |
| C63 AMG | 14-15 | AP1291 | R1291 | | HB731.620 | AP1450 | RC1450 | | HB808.570 |
| C63 AMG/S Silver Cal | 16-18 | AP1873 | | | | AP1669 | RC1669 | | HB844.700 |
| C63 AMG/S Red Cal | 16-20 | AP1291 | R1291 | | HB731.620 | AP1669 | RC1669 | | HB844.700 |
| E63 AMG | 10-17 | AP1291 | R1291 | | HB731.620 | AP1450 | RC1450 | | HB808.570 |
| SLS | 11-14 | AP1291 | R1291 | | HB731.620 | AP1607 | | | HB824.668 |

Application Guide

| MG | | FRONT | | | | REAR | | | |
|----------------------------|-------|-----------------------|-----------------------|-----|---------------------------|-------------------------|-----|-----|------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| MGA (DOHC) | 58-62 | DD704 | | | | DD704 | | | |
| MGB,MGB GT | 62-80 | LD10 | LD10 | | HB132.580 | SHOE437 | | | |
| MGC | 68-69 | AP114 | RC114 | | HB169.560 | SHOE409 | | | |
| Midget | 63-79 | LD15 | LD15 | | HB123.535 | SHOE216 | | | |

| MITSUBISHI | | FRONT | | | | REAR | | | |
|---------------------------------|-------|------------------------|-----------------------|----------------------|---------------------------|-------------------------|-----------------------|----------------------|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| Eclipse V6 | 06-12 | AP866 | RC866 | | HB435.622 | AP532 | | 0532 | HB673.602 |
| Lancer EVO | 03-06 | AP1001 | R1001 | 7781 | HB453.585 | AP961.1 | R961 | 7824 | HB180.590 |
| Lancer EVO | 08-16 | AP1001 | R1001 | 7781 | HB453.585 | AP1368 | R1368 | | HB615.535 |
| Lancer Ralliart | 10-16 | AP530 | RC530 | 0530 | HB214.618 | AP868 | | | HB675.602 |
| Lancer GT/S | 10-16 | AP866 | RC866 | | HB435.622 | AP868 | | | HB675.602 |

| NISSAN | | FRONT | | | | REAR | | | |
|-------------------------------|-------|------------------------|------------------------|----------------------|---------------------------|-------------------------|------------------------|----------------------|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| 240,260,280Z | 70-75 | AP114 | RC114 | | HB169.560 | SHOE411 | | | |
| 280Z | 76-78 | AP114 | RC114 | | HB169.560 | SHOE480 | | | |
| 280ZX, Turbo | 79-81 | AP229 | RC229 | | | AP213 | RC213 | | |
| 280ZX, Turbo | 82-83 | AP229 | RC229 | | | AP272 | RC230 | | HB262.540 |
| 300ZX, Turbo | 89-96 | AP460 | RC460 | 0460 | HB178.564 | AP461 | RC461 | 0461 | HB179.630 |
| 510 | 68-73 | DAT510 | RC37 | | | SHOE359 | | | |
| GT-R | 09-21 | AP1382 | RC1382 | 4362 | HB650.730 | AP1383 | R780 | 7780 | HB193.670 |
| 370Z Alum Cal | 09-20 | AP1346 | RC1346 | 1346 | HB601.626 | AP1347 | RC1347 | 1347 | HB602.545 |

| PORSCHE | | FRONT | | | | REAR | | | |
|--------------------------------|-------|------------------------|------------------------|----------------------|---------------------------|------------------------|-----------------------|----------------------|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| 356 | 63-65 | AP31 | R31 | 0031 | HB172.595 | AP30 | RC30 | | HB713.585 |
| Boxster | 97-04 | AP737 | RC737 | 0737 | HB289.610 | AP738 | RC738 | 0738 | HB290.583 |
| Boxster | 05-08 | AP737 | RC737 | 0737 | HB289.610 | AP1134 | RC738 | 0738 | HB665.577 |
| Boxster | 09-12 | AP1135 | RC776 | 0776 | HB664.634 | AP1134 | RC738 | 0738 | HB665.577 |
| Boxster / S | 13-16 | AP1389 | RC1389 | 1389 | HB719.668 | AP1134 | RC738 | 0738 | HB665.577 |
| Boxster S | 00-07 | AP917 | RC776 | 0776 | HB550.634 | AP738 | RC738 | 0738 | HB290.583 |
| Boxster S | 08-12 | AP1135 | RC776 | 0776 | HB664.634 | AP1134 | RC738 | 0738 | HB665.577 |
| Boxster Spyder | 2016 | AP1664 | RC1664 | | HB907.640 | AP1655 | | 7727 | HB829.594 |

| PORSCHE | | FRONT | | | | REAR | | | |
|--------------------------------------|-------|------------------------|------------------------|----------------------|---------------------------|------------------------|------------------------|----------------------|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| Boxster/Cayman 718 | 17-20 | AP1389 | RC1389 | 1389 | HB719.668 | AP1134 | RC738 | 0738 | HB665.577 |
| Boxster/Cayman 718 S | 17-20 | AP1905 | | | | AP1134 | RC738 | 0738 | HB665.577 |
| 911 A Caliper | 75-77 | AP45 | R45.15 | 0045 | HB171.590 | AP31 | R31 | 0031 | HB172.595 |
| 911 M Caliper | 70-77 | AP31 | R31 | 0031 | HB172.595 | AP31 | R31 | 0031 | HB172.595 |
| 911 S Caliper | 69-77 | AP45T | R45.19 | | HB171.720 | AP31 | R31 | 0031 | HB172.595 |
| 911 | 78-89 | AP45 | R45.15 | 0045 | HB171.590 | AP31 | R31 | 0031 | HB172.595 |
| 911 C4/S | 89-94 | AP345 | R608 | 0345 | HB170.650 | AP345 | R608 | 0345 | HB170.650 |
| 911 C2 | 90-91 | AP345 | R608 | 0345 | HB170.650 | AP483 | | | |
| 911 C2 964 | 92-94 | AP345 | R608 | 0345 | HB170.650 | AP345 | R608 | 0345 | HB170.650 |
| 911 C2 993 | 94-98 | AP372 | R609 | 0447 | HB141.650 | AP345 | R608 | 0345 | HB170.650 |
| 911 C4 | 95-98 | AP372 | R609 | 0447 | HB141.650 | AP345 | R608 | 0345 | HB170.650 |
| 911 C2 996 | 98-05 | AP917 | RC776 | 0776 | HB550.634 | AP738 | RC738 | 0738 | HB290.583 |
| 911 C4 996 | 99-05 | AP917 | RC776 | 0776 | HB550.634 | AP738 | RC738 | 0738 | HB290.583 |
| 911 C2 997 | 05-08 | AP1135 | RC776 | 0776 | HB664.634 | AP738 | RC738 | 0738 | HB290.583 |
| 911 C4 997 | 06-08 | AP1135 | RC776 | 0776 | HB664.634 | AP738 | RC738 | 0738 | HB290.583 |
| 911 C2 & C4 | 09-12 | AP1389 | RC1389 | 1389 | HB719.668 | AP1300 | RC1300 | 1299 | HB651.624 |
| 911 C2 & C4 | 13-16 | AP1389 | RC1389 | 1389 | HB719.668 | AP1655 | | 7727 | HB829.594 |
| 911 Carrera | 17-21 | AP1905 | RC1905 | | | AP1417 | RC1417 | | |
| 911 C2S | 91-94 | AP372 | R609 | 0447 | HB141.650 | AP345 | R608 | 0345 | HB170.650 |
| 911 C2S & C4S | 96-98 | AP594 | RC594 | 0594 | HB184.650 | AP372 | R609 | 0447 | HB141.650 |
| 911 C4S | 02-05 | AP916 | RC916 | 7818 | HB667.622 | AP917 | RC776 | 0776 | HB550.634 |
| 911 C2S & C4S | 06-12 | AP916 | RC916 | 7818 | HB667.622 | AP1135 | RC776 | 0776 | HB664.634 |
| 911 C2S & C4S | 13-16 | AP1664 | RC1664 | | HB907.640 | AP1417 | RC1417 | | HB807.587 |
| 911 C2S | 17-21 | AP1741 | RC1741 | 1773 | HB905.646 | AP1417 | RC1417 | | |
| 911 Turbo | 91-92 | AP372 | R609 | 0447 | HB141.650 | AP345 | R608 | 0345 | HB170.650 |
| 911 Turbo | 93-94 | AP594 | RC594 | 0594 | HB184.650 | AP345 | R608 | 0345 | HB170.650 |
| 911 Turbo | 95-98 | AP594 | RC594 | 0594 | HB184.650 | AP372 | R609 | 0447 | HB141.650 |
| 911 Turbo | 01-05 | AP916 | RC916 | 7818 | HB667.622 | AP917 | RC776 | 0776 | HB550.634 |
| 911 Turbo | 07-13 | AP991 | RC991 | 7819 | HB483.635 | AP1300 | RC1300 | 1299 | HB651.624 |
| 911 Turbo | 14-17 | AP1741 | RC1741 | 1773 | HB905.646 | AP1740 | RC1740 | 7727 | HB850.655 |
| 911 GTS | 11-12 | AP916 | RC916 | 7818 | HB667.622 | AP1135 | RC776 | 0776 | HB664.634 |
| 911 GT2/GT3 | 02-05 | AP991 | RC991 | 7819 | HB483.635 | AP993 | RC776 | 0776 | HB550.634 |

***This is a sampling of the more popular models if your vehicle isn't listed
[Click here](#) to search our site*** ALL Listings are for NON Ceramic discs

Application Guide

| PORSCHE | | FRONT | | | | REAR | | | |
|-------------|-------|------------------------|------------------------|----------------------|---------------------------|------------------------|------------------------|----------------------|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| 911 GT3 | 07-08 | AP991 | RC991 | 7819 | HB483.635 | AP1300 | RC1300 | 1299 | HB651.624 |
| 911 GT3 | 10-11 | AP1431 | | | | AP1300 | RC1300 | 1299 | HB651.624 |
| 911 GT3 | 14-19 | AP1741 | RC1741 | 1773 | HB905.646 | AP1740 | RC1740 | 7727 | HB850.655 |
| 914-4 | 70-72 | AP31 | R31.15 | 0031 | HB172.595 | AP30 | RC30 | | HB713.585 |
| 914-4 | 73-76 | AP31T | R31.18 | | | AP30 | RC30 | | HB713.585 |
| 914-6 | 70-72 | AP31 | R31.15 | 0031 | HB172.595 | AP31 | R31.15 | 0031 | HB172.595 |
| 924,S,Turbo | 81-84 | AP251 | RC251 | | HB199.702 | AP252 | RC252 | | HB198.685 |
| 928 | 86-91 | AP372 | R609 | 0447 | HB141.650 | AP345 | R608 | 0345 | HB170.650 |
| 928 | 92-95 | AP594 | RC594 | 0594 | HB184.650 | AP345 | R608 | 0345 | HB170.650 |
| 930 Turbo | 76-77 | AP45T | R45.19 | | HB171.720 | AP31 | R31.15 | 0031 | HB172.595 |
| 930 Turbo | 78-79 | AP345 | R608 | 0345 | HB170.650 | AP345 | R608 | 0345 | HB170.650 |
| 944 | 83-89 | AP251 | RC251 | 0443 | HB199.702 | AP252 | RC252 | | HB198.685 |
| 944 Turbo | 86-88 | AP345 | R608 | 0345 | HB170.650 | AP345 | R608 | 0345 | HB170.650 |
| 944 Turbo | 89-91 | AP372 | R609 | 0447 | HB141.650 | AP345 | R608 | 0345 | HB170.650 |
| 968 | 92-95 | AP345 | R608 | 0345 | HB170.650 | AP345 | R608 | 0345 | HB170.650 |
| 968 Sport | 92-95 | AP372 | R609 | 0447 | HB141.650 | AP345 | R608 | 0345 | HB170.650 |

| TOYOTA | | FRONT | | | | REAR | | | |
|----------------------|-------|------------------------|-----------------------|----------------------|---------------------------|------------------------|-----------------------|-----|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| 86 TRD Editn | 19-20 | AP1001 | R1001 | 7781 | HB453.585 | AP961 | R961 | | HB180.560 |
| Corolla GTS | 87-91 | AP242 | RC242 | | HB191.590 | AP352 | | | HB401.587 |
| GR Supra 2.0 | 2021 | AP1892 | | | | AP2221 | | | |
| GR Supra 3.0 | 20-21 | AP1867 | | | HB916.740 | AP2221 | | | |
| GR Supra 3.0 Premium | 20-21 | AP1867 | | | HB916.740 | AP2220 | | | HB917.626 |
| MR2 | 85-95 | AP242 | RC242 | | HB191.590 | AP309 | RC309 | | |
| MR2 | 00-05 | AP822 | RC822 | | HB493.650 | AP309 | RC309 | | |
| MR2 Turbo | 92-95 | AP582 | RC582 | | | AP309 | RC309 | | |
| Supra | 81-85 | AP245 | RC245 | | | AP240 | RC240 | | |
| Supra | 86-92 | AP435 | RC435 | | | AP432 | RC432 | | |
| Supra Turbo | 93-98 | AP629 | RC629 | | HB215.630 | AP630 | RC630 | | HB216.590 |

| SUBARU | | FRONT | | | | REAR | | | |
|---------------------|-------|------------------------|------------------------|----------------------|---------------------------|------------------------|------------------------|----------------------|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| BRZ | 13-15 | AP1539 | RC1539 | | HB711.661 | AP1114 | RC1114 | | HB557.545 |
| BRZ w/Vented R/Disc | 13-20 | AP1539 | RC1539 | | HB711.661 | AP1124 | RC1124 | | HB671.628 |
| BRZ w/Brembo | 17-20 | AP1001 | R1001 | 7781 | HB453.585 | AP961 | R961 | 7824 | HB180.560 |
| Impreza Coupe | 11-16 | AP1539 | RC1539 | | HB711.661 | AP1114 | RC1114 | | HB557.545 |
| WRX | 06-07 | AP1182 | RC460 | 0460 | HB178.564 | AP461 | RC461 | 0461 | HB179.630 |
| WRX | 08-10 | AP929 | RC929 | 0929 | HB432.661 | AP1114 | RC1114 | | HB557.545 |
| WRX | 11-14 | AP1539 | RC1539 | | HB711.661 | AP1114 | RC1114 | | HB557.545 |
| WRX | 15-21 | AP1078 | RC1078 | | HB533.668 | AP1114 | RC1114 | | HB557.545 |
| WRX STi | 02-17 | AP1001 | R1001 | 7781 | HB453.585 | AP961 | R961 | 7824 | HB180.560 |
| WRX STi | 18-21 | AP1365 | RC1365 | | HB616.607 | AP2118 | | | HB914.580 |

| TRIUMPH | | FRONT | | | | REAR | | | |
|-----------|-------|-----------------------|-----------------------|----------------------|---------------------------|-------------------------|-----|-----|------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| Spitfire | 62-67 | GD528 | | | | SHOE318 | | | |
| Spitfire | 67-80 | GD533 | R44 | 0044 | HB118.560 | SHOE318 | | | |
| TR250,TR6 | 68-72 | AP114 | RC114 | | HB169.560 | SHOE234 | | | |
| TR3, 3A | 59-62 | GD500 | GD500 | | | SHOE | | | |
| TR4, 4A | 61-67 | AP114 | RC114 | | HB169.560 | SHOE234 | | | |
| TR7 | 75-81 | LD15 | LD15 | | | SHOE484 | | | |
| TR8 | 78-81 | LD40 | | | HB229.580 | SHOE484 | | | |
| GT6 | 66-72 | AP114 | RC114 | | HB169.560 | SHOE211 | | | |
| GT6 | 72-74 | AP114 | RC114 | | HB169.560 | SHOE234 | | | |

| TESLA | | FRONT | | | | REAR | | | |
|---------------|-------|--------------------------|-----------------------|----------------------|---------------------------|-------------------------|----------------------|----------------------|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| S4pist Rear | 12-20 | AP1474.1 | R1001 | 7781 | HB453.585 | AP592.1 | R592 | 0592 | HB663.557 |
| 3 | 18-21 | AP2195 | | | | AP2283 | | | |
| 3 Perf Brakes | 18-21 | AP2399 | | | | AP2387 | | | |

| VOLKSWAGEN | | FRONT | | | | REAR | | | |
|---------------|-------|-------------------------|------------------------|-----|---------------------------|------------------------|------------------------|-----|---------------------------|
| Model | Year | Port | Ray | PFC | Hawk | Port | Ray | PFC | Hawk |
| GTi | 06-10 | AP1107 | | | HB543.760 | AP1108 | RC1108 | | HB544.628 |
| GTi | 11-13 | AP1107 | | | HB543.760 | AP1456 | | | HB695.609 |
| GTi | 15-18 | AP1760 | | | HB788.745 | AP1779 | | | HB836.651 |
| GTi w/Prf Pkg | 15-20 | AP1633 | RC1633 | | HB779.740 | AP1108 | RC1108 | | HB544.628 |
| Golf R / R32 | 2004 | AP682 | | | HB497.776 | AP340 | R1017 | | HB364.587 |
| Golf R / R32 | 2008 | AP915.3 | RC915 | | HB515.760 | AP1108 | RC1108 | | HB544.628 |
| Golf R / R32 | 12-13 | AP1111 | | | HB538.760 | AP1108 | RC1108 | | HB544.628 |
| Golf R / R32 | 15-19 | AP1633 | RC1633 | | HB779.740 | AP1761 | RC1761 | | HB789.600 |