

TECHNICAL SERVICE BULLETIN Number: TSB-COM VAC-2020-001

Model & GD930— SWITCH ON/OFF

Symptom:

Date: December 3, 2020

Author: Alberto Rastelli

Urgency:  HIGH: Immidiate is required. Service must be schedule	ce visit machine is exhibiting the machine is exhibiting the next scheduled visit to machine is exhibiting the
Informational Bulletin:	
Discontinue P/N 140 7033 500, SWITCH ON/OFF 930-SERIES	
PRODUCTS:	
GD930 / 930S2	
SPARE PART	'S and/or SPARE PART KITS:
140 7033 500 - SWITCH ON/OFF is closed and replaced by	
107408927 - new SWITCH ON/OFF + one of the stands:	
107413587	STAND BLACK <b>ON-OFF</b> ONLY W POWER OUTLET
107413588	STAND BLACK <b>DUAL</b> SPEED W POWER OUTLET
107413589	STAND BLACK ON-OFF ONLY W POWEROUTLET <b>US</b>

QMS-2-SER0336-03 Page 1