

Dust Cap Installation Instructions



Step 1

Check that you have all the correct parts. The white caps are small so be careful you don't lose them when opening the package. You should have 2, 1 tether and 1 eyelet

Step 2

Place the dust cap on to the correct end of the cable. This confirms that it is the correct fit.



Step 3

On the base of the cable, there are either 2 or 3 small holes for mounting dust cap cable to. Check which hole provides the correct level of slack in the dust cap cable and insert the white eyelet into it.

Step 4

Place the dust cap cable over the top of the eyelet installed in Step 3. Push the tether through it. You will hear a distinctive click, indicating that it is installed correctly.



Your Dust Cap is now installed.

If you are adding one to each end, repeat the process for the other end of the cable.

If you require any additional help don't hesitate to get in contact.

