
ADAPTIV MOTORCYCLE ACCESSORY MOUNT

SPORTBIKE MOUNT INSTALLATION



CONTENTS



Item No.	Name	Qty.
1	Steering Stem Nut	1
2	Left Link	1
3	Right Link	1
4	Positioning Screw	1
5	Positioning Lock Washer	1
6	Mounting Plate	1
7	5/32" Hex Key	1

This Mount is designed to be used on motorcycles with a steering stem nut.



Warning: Installation of the mount should be performed by a qualified technician. Improper installation may interfere with the safety and proper operation of the product and/or vehicle.

- 1. Place the motorcycle on a center stand.
- Using the 5/32" Hex Key, remove the Positioning Screw and Positioning Lock Washer to disassemble the Mount as shown in Figure 1.




Figure 1

- 3. Remove the stock Steering Stem Nut (also known as Yoke Nut) on the motorcycle and replace with the supplied Steering Stem Nut. Tighten to 70% of the vehicle manufacturer's torque specification. Note that the stock washer should be reused.
- Tip: Wrap the Steering Stem Nut in multiple layers of masking tape or a shop rag to prevent damage from the wrench.
- 4. Using the 5/32" Hex Key, loosely reassemble the Mount as shown in **Figure 2**.




Figure 2

5. Fasten the accessory device or cradle to the top of the Mounting Plate (Figure 3) utilizing appropriate hardware. The eight "AMPS" pattern holes (1-8) will accommodate #8 or M4 screws. The larger hole (9) will accommodate a 1/4" or M6 screw. Alternatively, double sided adhesive tape or hook and loop fastener may be used.




Figure 3

Adjust the mount to the desired position and tighten the *Positioning Screw* to lock the assembly in place.



Warning: Verify that the position of the mount and accessory will not interfere with proper operation of the vehicle.



Warning: Make sure all screws and nuts are securely tightened before each ride so that the assembly will not move during use.

Adaptiv Technologies, LLC

1639 11th Street Suite 156 Santa Monica, CA 90404

www.AdaptivTech.com

866-ADAPTIV (866-232-7848) 646-722-0253