

Hardware List


No.	Name	Picture	Qty.	No.	Name	Picture	Qty.
1	Lengthening big buckle bar	02	8	7	Dia. 6mm flat washer		16
2	Large buckle wheel		8	8	M8 load binder		4
3	M6*12 cross round head galvanized screw		8	9	M8*50 cross round head galvanized screw		12
4	M8*70 cross round head galvanized screw		4	10	Diameter 16 rubber foot nails		2
(5)	M6*45 cross chamfered galvanized screw		10	11)	Iron triangle		2
6	Dia. 6mm flat washer		10				





- 1. The leg 4 install 10.
- 2. The 5 adopts ① and ② to connect the 4.3. The 4 adopts ① and ② to connect the 1 and 3

- 4. The 1 adopts 3 to connect the 1,3 and 5.
- 5. The 2 using 9 and 7 connected to the 1 and 3. At the same time, the 2 adopts (5) and (6) to connect the 5.



	Itme	Name	Spec.	Qty
	1	Left bedside	1972X130	1
	2	Bedstead		1
,	3	Right bedside	1972X130	1
	4	Bed leg	290X65	2
	5	Footboard	1744X130	1

6、


a.The Bedstead 2 adopts (5) and (6) to connected with the matching headboard.

b.The 1 and 3 adopts 4,7 and 8 to connected the matching headboard,


Installation complete

Hardware List


No.	Name	Picture	Qty.	No.	Name	Picture	Qty.
1	Diameter 16 rubber foot nails		10	7	8*40 Wood tip		2
2	Galvanized connecting iron plate 60*40mm		3	8	M6*50 cross chamfered galvanized screw		4
3	M3.5*14 cross countersunk head self-tapping nail		68	9	Dia. 6mm flat washer		4
4	Angle iron 4 holes		14	10	M4*25 cross countersunk head self-tapping nail		3
(5)	Large buckle wheel		12	11)	Diameter 4 concave pad		3
6	Big buckle bar		12				




- 1、
- a. The bottom of the 2 and 3 are installed with (1).
- b. The 2 adopts (5) and (6) to connect the 3.




2. The 6 adopts 5 and 6 to connect the 4 and 5.




- 3′
- a. The 1 adopts 7 to connect the 4 and 5.
- b. The 1 adopts (8) and (9) to connect and fix the 4 and 5.



- 4. a. As shown in the picture, use two groups of ④ and ③ to connected and fixed on the upper end of the 2 (one on the left and one on the right). Use one set of ④ and ③ to connected and fixed at the lower end of the 2. b. When the 1 is aligned with the 3, then the ④ on the 2 use ③ to connected 1 and 3.
- c. The 4 and 5 are connected with (4) and (3) to reinforce the 3.
- d. The 6 adopts (10) and (11) to connect and reinforce the 1.
- e. Use ② and ③ to connect the 6 and 3, the installation is completed





Itme	Name	Spec.	Qty
1	Combined backrest		1
2	Support plate	950X76	4
3	Combined bed box panel		1
4	Left lateral column of backrest	433X84	1
5	Right lateral column of backres	433X84	1
6	Bottom crossband of backrest	1820X84	1