VESDA VLF MCC



The VESDA VLF MCC (Multi-function Control Card) is an interface card for the range of Xtralis VESDA VLF smoke detectors. An MCC expands the range of input and output communications a VLF detector can perform.

Why use a VLF MCC?

Installing a VLF MCC into a VLF detector provides a cost-effective solution for customers who need enhanced connectivity, fault detection and monitoring, and annunciation of alarms and faults. The principal benefits include:

Improved FACP connectivity

The VLF is fitted with two (2) alarm relays in its standard form. With an extra two (2) relays, the Multi-function Control Card allows reporting of all four (4) alarm levels on dry relay outputs.

Enhanced annunciation

An MPO (Monitored 24 V Powered Output) is available on the VIC-030 version of the card. The MPO provides power to devices such as sirens or strobes, and monitors the line integrity.

Enhanced control and fault detection

With a VLF MCC installed, a VLF has two (2) General Purpose Inputs (GPIs), allowing, for example, one GPI to report on loss of mains power and the other GPI to be used as a reset input.

The VIC-030 version of the card has a self-configuring GPI, depending on the jumper selection for MPO/Relay3.

- If MPO is selected, activation of the GPI will disable the MPO.
- If Relay3 is selected, the GPI will be set to External Fault (e.g. for mains power supply monitoring).

VIC-020 & VIC-030

Features

VIC-020

- · Provides two (2) additional relays
- Provides an extra General Purpose Input (GPI) with line monitoring
- · Quick and simple to install
- Out-of-the-box operation, with minimal configuration required for extra features
- Diagnostic LEDs give visual indication of the card's status
- Fully compatible with Xtralis VESDA VLF smoke detectors

VIC-030

- As above, plus:
- Selection between 3rd relay or 24 V Monitored Powered Output (MPO)



VESDA VLF MCC

Specifications

Dimensions

Length x Width x Height 110 mm (41/3") x 70 mm (2 3/4") x 20 mm (13/16")

Weight 0.08 kg (0.176 lb)

Terminals 0.2 - 2.5 mm2 (30-12 AWG)

Electrical Ratings

Power consumption 1 W from the detector at 24 VDC (less than 42 mA)

Relay outputs 2 A at 30 VDC 24 VDC (VIC-030 only) MPO input power supply

100 mA more than MPO output load (VIC-030 only) MPO input current

1 A (maximum) (VIC-030 only) MPO output current

End of line resistor (MPO & GPI) 2 7K Ohm

Operating Conditions

Tested to -10 to 55°C (14 to 131°F) Detector ambient temperature 0 to 40°C (32 to 104°F) Humidity 5% to 95% (non-condensing)

Detector Compatibility

Supports VLF-250 and VLF-500

Product Warranty

2 years

Input/Output Assignments

VIC-020

Output for Relay 1: ALERT (follows latching configuration of VLF ALERT status) Output for Relay 2: FIRE-2 (follows latching configuration of VLF FIRE-2 status)

Input for GPI: **FAULT**

GPI reports status on following conditions:

- EOL > No fault

- Short > Fault # 115/IFF6 - O/C > Fault # 111/IFF8

VIC-030

Output for Relay 1: ALERT (follows latching configuration of VLF ALERT status) Output for Relay 2: FIRE-2 (follows latching configuration of VLF FIRE-2 status)

MPO: ALERT (unless disabled) (follows latching configuration of

VLF ALERT status) **dumper** configuration • • • J9 J10

Disable MPO GPI for MPO:

MPO status is driven as follows:

- EOL > MPO enabled - Short > MPO disabled*

- O/C > MPO enabled and Fault # 111/IFF8

Output for Relay 3: DISABLED or STANDBY (follows VLF DISABLED or STANDBY status)

> Jumper configuration • • .19 J10

GPI for Relay 3: **FAULT**

GPI reports status on following conditions:

- EOL > No fault

- Short >Fault # 115/IFF6 O/C > Fault # 111/IFF8

* The MPO is disabled if there is a short on the GPI.

VIC-020 & VIC-030

Terminal Block Connections

0	GPI+
0	GPI-
0	NO1
0	COM1
0	NC1
0	NO2
0	COM2
0	NC2
0	NO3 / MPO+ 1
0	COM3 / MPO - 1
9	NC3 / 0VDC ¹
9	MPO 24VDC ¹
_	

Visual Status Indicators

Diagnostic LEDs indicate:

- · power to the MCC
- power to the MPO (VIC-030 only)
- · relay activated state
- MPO activated state (VIC-030 only)
- · MPO power and line fault (VIC-030 only)
- · internal communications status
- · GPI state
- · GPI line fault

Ordering Information

Product Part number VESDA VLF MCC VIC-020

VESDA VLF MCC

with MPO VIC-030

Includes: control card, interface cable, single screw, field wiring connectors and end of line resistor(s) (one resistor for VIC-020 or two resistors for VIC-030).

www.xtralis.com

The Americas +1 781 740 2223 Asia +852 2916 8894 Australia and New Zealand +61 3 9936 7000 Continental Europe +32 56 24 1951 UK and the Middle East +44 1442 242 330

The contents of this document are provided on an "as is" basis. No representation or warranty (either express or implied) is made as to the completeness, accuracy or reliability of the contents of this document. The manufacturer reserves the right to change designs or specification without obligation and without further notice. Except as otherwise provided, all warranties, express rimplied, including without limitation any implied warranties of merchantability and fitness for a particular purpose are expressly excluded.

This document includes registered and unregistered trademarks. All trademarks for a particular trademarks of their respective owners. Your use of this document does not constitute or create a licence or any other right to use the name and/or trademark and/or label.

This document is subject to copyright owned by Xtralis AG ("Xtralis"). You agree not to copy, communicate to the public, adapt, distribute, transfer, sell, modify or publish any contents of this document without the express prior written consent of Xtralis.

Doc. no. 11433 14 Part: 20527



¹ available only on VIC-030