



Still Use Traditional Thermometer?



You Need a Intelligent Thermometer

0.1s Quick Measurement
Non-Contact, avoid cross-infection



High Accuracy: ±0.2 Degrees




High Temperature Alarm
Abnormal temperature: flashing red lights and alarm "DUE"



Can Be Used in a Variety Of Places
Superior for schools, homes, supermarkets, shops, community, conference, etc.



Install Method



Appearance

