

Total Quality. Assured. TEST REPORT

Applicant:

MAYSTAR FOOTWEAR CO., LTD NO. 3047 MINGZHU SOUTH RD., CUIWEI INDUSTRIAL DISTRICT, QIANSHAN ZHUHAI GUANGDONG Attn: LI.LY CONNIE

Sample Description:

Three (3) pairs of submitted samples said to be Men's safety shoes samples in Grey (INVADER ST /P91276).				
Standard :	ASTM F2413-18			
Size :	MEN'S US 9			
Brand :	CATERPILLAR			
Style Name/Stock No. :	INVADER ST , P91274 / P91275 / P91276			
Safety Toe Cap/Supplier Name :	NT085/ LYTER			
Outsole/Supplier Name :	T1455 RB2 RUBBER OUTSOLE/WAN WEI			
Manufacturer :	KINGMAKER (VN) FOOTWEAR CO LTD			
PS No. :	PS-597-18			
Date Received/Date Test Started:	Jul. 15, 2020			
Date Final Information Confirmed:	Jul. 24, 2020			

Test Result Please Refer To Attached Page(S).

Should you have any query on this report, you may contact at gzfootwear@intertek.com

Authorized By: For Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

Guiliang Dong Senior Lab Manager



EC / lydiayang

Page 1 Of 3

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司 Room 02, 1-8/F. & Room 01, E101/E201/E301/E401/E501/E601/E701/E801, 3/F., Hengyun B No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou, Guangdong, China 广州经济技术开发区科学城彩频路 7 号之二第 1-8 层 02 房、01 房 101、 China E201、E301、E401、E501、E601、E701、E801 中国广州经济技 Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510663 Tel: +86 20 839

3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou Economic & Technological Development District, Guangzhou, China 中国广州经济技开发区开发大道 235 号恒运大厦 3 楼

Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730



intertek Total Quality. Assured.

TEST REPORT



Tests Conducted (As Requested By The Applicant)

1 Protective Toe Impact Resistance (I) (ASTM F2412-18a, 5, Testing Performed At 22°C (\pm 2 °C) And 50 % RH (\pm 5 %))

		<u>ASTM F2413-18</u>	Pass/Fail
		Requirement	
	Interior Height Clearance		
Left:	14.8 mm	≥ 12.7 mm	Pass
Right:	16.7 mm	≥ 12.7 mm	Pass
Left:	16.2 mm	≥ 12.7 mm	Pass

2 Protective Toe Compression Resistance (C) (ASTM F2412-18a, 6, Testing Performed At 22°C (\pm 2 °C) And 50 % RH (\pm 5 %))

		<u>ASTM F2413-18</u>	Pass/Fail
		<u>Requirement</u>	
	Interior Height Clearance		
Left:	16.3 mm	≥ 12.7 mm	Pass
Right:	16.9 mm	≥ 12.7 mm	Pass
Right:	17.8 mm	≥ 12.7 mm	Pass

Bill State Conditions
3 Electric Hazard Resistant Footwear (EH) (ASTM F2412-18a, 9, Conditioned At 22°C (±2°C) And 50 % RH (± 5 %) For 24 h And Testing Performed At The Same Conditions.)

	Leakage Current	ASTM F2413-18 Requirement	Pass/Fail
Left:	0.2 mA	*	Pass
Right:	0.2 mA	*	Pass
Right:	0.2 mA	*	Pass

Remark: * = No Current Flow Or Leakage Current In Excess of 1.0 mA Under The Application Of 18 000 V At 60 Hz AC For 1 Minute.

/ lydiayang

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司
401/E501/E601/E701/E801,
8 层 02 房、01 房 101、
9 stcode: 510663
3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou
B conomic & Technological Development District, Guangzhou,
China
中国广州经济技开发区开发大道 235 号恒运大厦 3 楼
Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730

Page 2 Of 3

Room 02, 1-8/F. & Room 01, E101/E201/E301/E401/E501/E501/E601/E701/E801, No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou, Guangdong, China 广州经济技术开发区科学城彩频路 7 号之二第 1—8 层 02 房、01 房 101、 E201、E301、E401、E501、E601、E701、E801 Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510663

intertek



Total Quality. Assured. <u>TEST REPORT</u> Tests Conducted (As Requested By The Applicant)



End Of Report

Page 3 Of 3

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. No copy of the test report(except for full text copy) shall be made without the written approval by Intertek.

/ lydiayang

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司 Room 02, 1-8/F. & Room 01, E101/E201/E301/E401/E501/E601/E701/E801, 3/F., Hengyun B No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou, Guangdong, China 广州经济技术开发区科学城彩频路 7 号之二第 1-8 层 02 房、01 房 101、 E201、E301、E401、E501、E601、E701、E801 Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510663 Tel: +86 20 839

3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou Economic & Technological Development District, Guangzhou, China 中国广州经济技开发区开发大道 235 号恒运大厦 3 楼 Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730