

Flat Technology PX23 Paris Table Base

jason.l





Flat Technology PX23

Paris Table Base

jason.l

Parts

A		x1	 Because of the edges of some parts before assembly may be sharp, please handle carefully. CAUTION		
B		x1			
C		x1			
D		x1	H		x4 1/4"(M6)
E		x2	I		x1
F		x2 1/2"(M12)	J		x6
G		x4	K		x1 T20H




Flat Technology PX23

Paris Table Base

jason.l


STEP 3

Recommended torque = 20N.m / 15lb.ft




⚠ DO NOT OVERTIGHTEN

STEP 4




STEP 5



Recommended torque = 55N.m / 40lb.ft (MAX)

STEP 6





Recommended torque = 20N.m / 15lb.ft

⚠ DO NOT OVERTIGHTEN

Flat Technology PX23


Paris Table Base

jason.l



Flat Technology SX26 Sydney **jason.l** Flip Top Table Base

STEP 11



**ASSEMBLY
DONE!**

