# Quadro Loop Legs 6P 120 Degree Workstation with Screens


www.jasonl.com.au

Need help!

Call us on 1300 527 665



Sizes: 1200x1200x700 mm



2 persons required for installation


# Quadro Loop Legs 6P 120 Degree Workstation with Screens

Sizes: 1200x1200x700 mm

www.jasonl.com.au

Need help!






## Quadro Loop Legs 6P 120 Degree Workstation with Screens

www.jasonl.com.au

## Need help!






# Quadro Loop Legs 6P 120 Degree Workstation with Screens

Sizes: 1200x1200x700 mm

## www.jasonl.com.au

## Need help!







Using Allen Key provided, attach 4 plastic brackets per leg **(F)** (as per picture above) using M6x20MM **(I)** Socket head screw. Do the same with Connector frame **(D)**. Connect Loop Legs **(C)** to Bottom of Quadro Legs **(B)** by using 4 bolts per leg



Using Allen Key provided, attach M8x20MM Socket head **(H)**-screw socket half way into leg for both legs **(B)** and into Connector frame **(D)**.





# Quadro Loop Legs 6P 120 Degree Workstation with Screens


www.jasonl.com.au


## Need help!

Call us on **1300 527 665** 



Sizes: 1200x1200x700 mm





Frame looks like this. Using Allen Key, attach beam (E) with Socket (G)


drilling the screws into the Tops.


## Quadro Loop Legs 6P 120 Degree Workstation with Screens

www.jasonl.com.au

## **Need help!**







Drop the desk mounted screen in between the two tops (A). Now please insert 2 rod brackets that will hold each screen to the desks on either side.

# Quadro Loop Legs 6P 120 Degree Workstation with Screens


www.jasonl.com.au

Need help!

Call us on **1300 527 665** 



120 Degree table top size: 1200x1200x700 mm



Second person to drill 4 holes into the brackets holes with provided wood screws into the underneath desktop. Please check the position of the rod brackets and bracket holes again before drilling the screws all the way through. Please tighten all the wood screws.

Once the 2 rod brackets are screwed in, you can slide the screen down until it fully rest over the brackets, standing between both table tops.

# Quadro Loop Legs 6P 120 Degree Workstation with Screens


www.jasonl.com.au

Need help!

Call us on **1300 527 665** 



120 Degree table top size: 1200x1200x700 mm



Using an allen key, please remove 3 caps from all screens. Bring 3 partitions towards one another and slide the 3-way 120 degree connector -down between the three screen uprights.