



HYBD-CLC-2


Step 1. Assemble left & right columns.



Step 3. Attach canopy cross bars; assemble canopy.



Step 2. Join 2-piece graphic bars together; attach top cross bar to column; align with arrow.






Step 4. Place canopy on columns. Tighten column top CBX clamps using Red/Black handle 5mm hex wrench.




HYBD-CLC-2

// SEG Graphic Insertion //



// Detail //



HYBD-CLC-2

Step 5. Attach fabric graphic.



Step 6. Attach wings.



HYBD-CLC-2

Step 7. Attach standoff header.

