













ASSEMBLY INSTRUCTION

G1997 - LAPTOP DESK


| No | Name of Component | Q.ty |
|----------|------------------------------------------------------------------------------------------------------|------|
| A |  Table top frame | 1 |
| B |  Leg frame | 2 |
| No | Name of Hardware | Q.ty |
| 1 | Bolt M6 x 35  | 8 |
| 2 | Washer Ø7/Ø15 x 1  | 8 |
| 3 | Allen key K4  | 1 |
| 4 | Bracket  | 2 |
| 5 | Tie  | 1 |
| 6 | Screw Ø4 x 20  | 2 |



ASSEMBLY INSTRUCTION

G1997 - LAPTOP DESK

Step 5



FINAL

