










ASSEMBLY INSTRUCTION

G6918 - SIDE TABLE

No	PARTS NAME	Q.ty (pcs)	STEP 1	STEP 2
A	 Side Table	1		
B	 Legs Frame	1 Set		

No	LIST OF HARDWARE	Q.ty (pcs)
①	Bolts M6x50 	5
②	Allen key K4 	1
③	Handles 	1
④	Flat screw Ø3.5 x 12 	2
Screwdriver (not included) 		

FINAL

