

No	LIST OF HARDWAR	RE	Q.ty (pcs)
1	Bolts M6x35		8
2	Spring Washers	0	8
3	Flat Washers		8
4	Allen key K4		1
(5)	Screw Ø4 x 30		24
6	Screw Ø4 x 40		3
7	Plastic bracket		4
8	Tie		2
9	Screw Ø4x20	<b>Community</b>	8







Ax1: Front Frame





B x2: Side Frame (Left -Right)





© x1: Back Frame
























# HINGE ADJUSTMENT INSTRUCTIONS


#### LATERAL ADJUSTMENT

by screw adjustment.




#### FRONT-TO-BACK

by slackening and retightening the hinge-arm mounting screw.




#### **VERTICAL ADJUSTMENT**

via slots on mounting plate by slackening and



## **ASSEMBLY**



### DISASSEMBLY

