



*Softap Permanent Cosmetics*

P.O. Box 2581

Danville, Ca 94526-7581

For free technical support call:(925) 248-6301 Fax: (925) 248-6305

To place an order call: 1 (800) 9 SOFTAP or (800) 976-3827

## **NEEDLE STERILIZATION INFORMATION**

Method of sterilization – EN validation method

The sterility assurance level is 10

Temperature: 50-55

Absolute relative humidity 50%

Sterilization time 14 hours

E. O. G. Gas 70 to 75%

Ethylene Oxide Residue:

Ethylene Oxide < 3ppm

Ethylene Chlorohydrin < 3ppm

Ethylene Glycol < 3ppm