

# DLA+ QUICKSTART GUIDE

## DLA+



- 1 Close all other running applications
- 2 Insert the JPRO® Fleet Service Software Bundle CD or the DLA+ Driver CD into your CD or DVD drive. You can also download the latest DLA+ drivers from:  
[www.JPROFleetProducts.com](http://www.JPROFleetProducts.com)

- If using the software CD, the installation program will begin automatically. Click the Install DLA drivers button to begin.
- If using the download drivers, begin the installation process by running the file you just downloaded

- 3 Connect the diagnostic cable to the vehicle port on the PC

- 4 Attach the diagnostic cable's connector to the diagnostic port on the vehicle

- 5 Plug the USB cable into the USB port on the PC. Connect the other end of the USB cable to the port labelled Computer on the DLA+

- Windows displays the Found New Hardware wizard. **NOTE: If the Found New Hardware Wizard fails to start, be sure that the USB cable is pushed completely into the adapter's USB port, the ignition switch is set to ON, and the adapter Power light is on**

- When asked to connect to Windows Update, select "No, not this time" and click Next
- Select "Install the software automatically" and click next.
- Click "Finish" to complete the installation and click next.



[www.JPROFleetProducts.com](http://www.JPROFleetProducts.com)



[www.noregon.com](http://www.noregon.com)