



6.0 Notes

6.1 For concentrations of ruthenium below 0.5 mg/L, the furnace procedure, Method 267.2, is recommended.

7.0 Precision and Accuracy

7.1 Precision and accuracy data are not available at this time.