

Surface Preparation

One of the most important steps in decal installation is surface preparation. Without a clean surface your decal will never stick and will be ruined. Use your soap and water mix to clean off the organic matter, dirt, mud, bugs, ect. Use your towel to make sure the surface is dry. The next step is to use the prep solvent to clean off the chemicals, wax, gas, oil, grease. You can then use denatured alcohol to ensure that the solvent is completely taken off. Soapy water can also be used at this step if denatured alcohol is unavailable to use. With the proper preparation any installation gets easier by eliminating the chance for contaminants to ruin your decal.