



## WXA50 Reset Procedure



Put the unit into standby.  
Hold down 'INPUT' and 'CONNECT'  
on the front panel simultaneously for  
5 seconds.