


RE COLORS



□ Vehicle with hot wire, flap, and pressure sensor



■ Vehicle with RB26DETT



a fire electric shock, or damage to electrical equipment may occur

To illumination power Elumination power CAUTION insulate connections and the ends of unused harnesses: otherwise

