VST-25 Dial Indicated Height Indicator With Mounting Kit Instructions

GOODSON


Tools and Supplies for Engine Builders
156 Galewski Drive • P.O. Box 847 • Winona, MN 55987-0847
Toll-Free 1-800-533-8010 • Local 507-452-1830 • www.goodson.com

VST-25

Please read instructions before using.

Mounting Instructions

1. Unpack components and make sure you have all necessary parts.



- 2. Remove bottom center bolt on the spring tester table. (Discard bolt as you will use the new longer one in the kit)
- 3. Install larger flat plate over the table and install new longer chamfered bolt and tighten. (Caution: **do not over tighten**, snug is all you need)
- 4. Remove one of the bolts from the locking collar; open the collar and install it on the shaft above top spring pad.
- 5. Slide the 4" long bolt through the back lug on the indicator then install the long sleeve over the bolt. Thread the bolt into the back side of locking collar.
- 6. Position locking collar and indicator assembly just above the top spring pad making sure you have preload on indicator and tighten. The springs you are testing will determine where you install the indicator assembly.
- 7. Remove the screw holding the height ruler in place and install new height ruler with the zero mark lined up with the top of lower spring table.
- 8. You are now ready to test springs with more accuracy.

