

DuraBumper™ Guards Eliminate Damage Caused by Housekeeping Equipment

Applicable Renovation Materials & Labor Prototype: Luxury Hotel | 200 Guestrooms | 6 Stories **Subtotal** Avg Cost Keys **Guestrooms** Paint Trim (Base and Crown) \$643.40 200 \$128,680 Paint Entry Doors, Closet Doors, Frames, and Grilles \$623.26 200 \$124.652 Vinyl Wallcovering (LY 54") \$2,163.82 200 \$432,764 Wall Base \$1,914.02 200 \$382,804 **Bathrooms** Paint Door and Trim \$129.44 200 \$25.888 Corridors Vinyl Wallcovering (LY 54") \$275.02 200 \$55,004 Millwork Base \$222.24 200 \$44,448 Renovation Cost¹ \$1,194,240 1. 2017 Hotel Cost Estimating Guide (pages 76-78)

Bumper Guards for Housekeeping Equipment

www.hvs.com/article/8028-2017-hotel-cost-estimating-guide

HSKP Equipment: 200 Guestrooms 10 Rooms per HSKP Staff					
Qty	Equipment	DuraBumper Guards	Item #	Cost / Unit	Subtotal
20	Vacuum Cleaners	Vacuum Bumper Guards	UB11SM	\$19.95	\$399
20	Housekeeping Attendant Carts	WrapAround Cart Bumpers	R-WACB	\$92.95	\$1,859
20	Housekeeping Carts	Corner Wheel Bumper Covers	WBC-5.0	\$43.00	\$860
3	Laundry Trucks	Vinyl Truck Bumper Systems	VTBS	\$125.00	\$375
3	Houseperson Carts	Poly Truck Bumper Systems	PTBS	\$149.00	\$447
6	Rollaway Beds	Rollaway Bed-leg Bumpers	RBLB	\$48.00	\$288

2. 2018 DuraBumper Guards Pricing www.DuraBumper.com/collections/janitorial-hotel-housekeeping

Total Cost - DuraBumper Guards² \$4,228 % of Renovation Cost 0.35%