

MH-C321_ZW500

ADD	PARAMETER	BYTE	RANGE	UNIT	DEFAULT	DETAIL
0x01	Watt Meter Report period	2	0x01-0x7fff	5s	720	5*720S=3600S=1hour
0x02	KWH Meter Report period	2	0x01-0x7fff	10min	6	6*10min=1 hour
0x05	Level Report Mode	1	1-2		2	1:Report destination leve in 5s 2:Report 10 percent level while running
0x07	Demo trip	1	0-1		0	1= first touch up/down button will activate demo trip only
0x08	LED brightness level	1	0-0x0a		0	
0x09	Demo trip and calibration	1	1		0	1=activate demo trip and calibration
0x0A	Auto calibration	1	1		0	1=activate calibration
FF	Factory setting	1	0x55		0x00	