






























ARMARIO 1 ECO TYP G



















NO	Dim.			Col.-No	Qty
1	714	296	16	1	2
2	596	180	16	1	1
3	905	300	16	1	1
4	905	300	16	1	1
5	602	322	18	1	1
6	602	322	18	1	1
7	250	132	16	1	1
8	250	132	16	1	1
9	511	112	16	1	1
10	568	268	16	1	2
11	523	253	3	1	1
12	916	289	3	1	1
13	916	289	3	1	1









ARMARIO 1 ECO TYP G









A1 x12  ø8x36	B4 x6 	B5 x6  ø15x12	G5 x6 	B11 x8  ø7x50	G4 x8 
E1 x4  H=0	E2 x4  H=0	D10 x14  USØ3,5x13	KL x4  L-64mm	UP6 x8  UPØ4x30	Z2 x4  Ø5
H5 x1  L-250mm	D8 x4  ESØ5x13	B3 x5  Ø1,4x25	G8 x1 	G20 x2 	G7 x8 
I11 x4 	UP11 x4  UPØ4x20	S1 x12 	L1 x1 	KR1 x1  Ø8	G2 x1 




ARMARIO 1 ECO TYP G


1

A1 x8	 ø8x36	B5 x4	 ø15x12	E2 x4	 H=0
H5 x1	 L-250mm	D8 x4	 ESØ5x13	G7 x8	








2

B4	
x4	







3

I11		UP11		G20	
x4		x4	UPØ4x20	x2	










4

E1	Ø26	D10	
x4	 H=0	x8	 USØ3,5x13






5

A1	B4	B5	
x4	 ø8x36	x2	
		x2	 ø15x12






6

B11		G4	
x4	Ø7x50	x4	




7





G5	
x2	




8







9





X=Y 90°




180°






10

KL		UP6	
x2	L-64mm	x4	UPØ4x30




11


B11		G4	
x4	Ø7x50	x4	





90°






12

G8	
x1	




13



G5	
x4	





14


$X=Y$ 90°


S1	
x10	









15






L1	
x1	

KR1	
x1	$\varnothing 8$



D10	
x2	US $\varnothing 3,5 \times 13$



16



17



18

