

All window A/C units **MUST** have **Digital Display** and **Automatic Restart**

Window A/C brands marked with * have a minimum *ON* cycle time set from the factory; using an oversized A/C from these brands may lead you to experience colder than set temperatures or ice ups. Please use the recommended size A/C.

A/C Secondary Sensor Guide and Mini-Split Installation Guide available at our "Library" at: <https://storeitcold.com/support-library/>

For Portable A/Cs, see WHYNTER brand on page 2

COMPATIBLE UNITS

IF YOUR A/C UNIT IS NOT LISTED HERE, COOLBOT CANNOT GUARANTEE ITS COMPATIBILITY

LG is our preferred brand

| BRAND | WINDOW A/C | | MINI-SPLIT A/C |
|------------------------------|--|--|---|
| ARCTIC KING* | Any Digital Display model | 12K BTU and above HAVE SECONDARY SENSOR | N/A |
| DAIKIN | N/A | | ONLY for 45°F and above applications MINI SPLITS HAVE SECONDARY SENSORS |
| DANBY* | Any Digital Display model Avoid models pre-2011 | 12K BTU and above HAVE SECONDARY SENSOR | N/A |
| FRIGIDAIRE* | Any Digital Display model Avoid models pre-2015 | Some 10K BTU and most above 12K BTU HAVE SECONDARY SENSOR | N/A |
| FUJITSU | N/A | | Any Mini Split model MINI SPLITS HAVE SECONDARY SENSORS |
| GE - GENERAL ELECTRIC | Any Digital Display Model Avoid models pre-2015 Avoid AHC Models | Some 10K BTU and most above 12K BTU HAVE SECONDARY SENSOR | N/A |
| GREE* | Coolani Model AUSTRALIA & NZ ONLY | 12K BTU and above HAVE SECONDARY SENSOR | N/A |
| HAIER | Any Digital Display model Avoid HWE Models | NO SECONDARY SENSOR | N/A |
| KELVINATOR* | Any Digital Display model AUSTRALIA & NZ ONLY Avoid CRF Models | 12K BTU and above HAVE SECONDARY SENSOR | N/A |
| LG | Any Digital Display model Avoid LW6017R model | NO SECONDARY SENSOR <i>* Dual Inverter Models HAVE Secondary Sensors</i> | Most Mini Splits MINI SPLITS HAVE SECONDARY SENSORS HSV models for 55°F+ ONLY |
| MITSUBISHI | N/A | | Mr Slim Series is a good choice MINI SPLITS HAVE SECONDARY SENSORS |
| SAMSUNG | Any Digital Display model | 12K BTU and above HAVE SECONDARY SENSOR | ONLY for 45°F and above applications MINI SPLITS HAVE SECONDARY SENSORS |

LIMITED EXPERIENCE A/C UNITS

Limited Experience - Limited Support A/C Units

We have some users with good results using these A/C units BUT
we do not have enough collective data to classify them as fully compatible

We are happy to help you during installation BUT we CANNOT GUARANTEE ITS COMPATIBILITY

| BRAND | WINDOW A/C | | MINI-SPLIT A/C |
|------------------------|---|----------------------|---|
| AMANA | Limited experience - Limited support | HAS SECONDARY SENSOR | N/A |
| CARRIER | N/A | | Central And South America ONLY ALL MINI SPLITS HAVE SECONDARY SENSORS |
| CIAC | N/A | | Central And South America ONLY ALL MINI SPLITS HAVE SECONDARY SENSORS |
| COMFORT AIRE | Limited experience - Limited support | HAS SECONDARY SENSOR | Central And South America ONLY ALL MINI SPLITS HAVE SECONDARY SENSORS |
| COMFORT STAR | N/A | | Central And South America ONLY ALL MINI SPLITS HAVE SECONDARY SENSORS |
| DENALI AIRE | Limited experience - Limited support | HAS SECONDARY SENSOR | N/A |
| FEDDERS | Limited experience - Limited support | HAS SECONDARY SENSOR | N/A |
| GARRISON | CANADA ONLY | HAS SECONDARY SENSOR | N/A |
| i-COOL | N/A | | Central And South America ONLY ALL MINI SPLITS HAVE SECONDARY SENSORS |
| INNOVAIR | N/A | | Central And South America ONLY ALL MINI SPLITS HAVE SECONDARY SENSORS |
| KOOL KING | Limited experience - Limited support | HAS SECONDARY SENSOR | N/A |
| LENNOX | N/A | | Central And South America ONLY ALL MINI SPLITS HAVE SECONDARY SENSORS |
| MIDEA | N/A | | Limited experience - Limited support |
| NOMA* | Limited experience - Limited support | HAS SECONDARY SENSOR | N/A |
| PERFECT AIRE* | Limited experience - Limited support | HAS SECONDARY SENSOR | N/A |
| PIONEER | N/A | | Limited experience - Limited support MAY HAVE SECONDARY SENSORS |
| RHEEM/RHUUD | N/A | | Central And South America ONLY ALL MINI SPLITS HAVE SECONDARY SENSORS |
| SEARS KENMORE | Limited experience - Limited support | HAS SECONDARY SENSOR | N/A |
| SHARP | Limited experience - Limited support | HAS SECONDARY SENSOR | Not Compatible |
| SOLEUS AIR | Limited experience - Limited support | HAS SECONDARY SENSOR | N/A |
| SPT | Limited experience - Limited support | HAS SECONDARY SENSOR | N/A |
| TOSHIBA | Limited experience - Limited support | HAS SECONDARY SENSOR | Not Compatible- Avoid |
| UBERHAUS | Limited experience - Limited support | HAS SECONDARY SENSOR | N/A |
| WESTPOINT | Limited experience - Limited support | HAS SECONDARY SENSOR | N/A |
| WHISPER AIR | N/A | | Central And South America ONLY ALL MINI SPLITS HAVE SECONDARY SENSORS |
| WHYNTER (PORTABLE A/C) | USE DUAL HOSE MODEL ONLY- HAS SECONDARY SENSOR ONLY for 54+°F applications | | |
| YORK | N/A | | Central And South America ONLY ALL MINI SPLITS HAVE SECONDARY SENSORS |

INCOMPATIBLE A/C UNITS

AVOID USING THE COOLBOT WITH THESE BRANDS

We cannot guarantee these brands will work with the CoolBot.

We suggest you try one of our supported brands.

BRAND

AMERICAN STANDARD

BEAUMARK

BLUERIDGE

BOSCH

COOL LIVING

DAEWOO

DEGODI

DELLA

DOMETIC

ELECTROLUX

EMERSON

FRIEDRICH

GOLDSTAR

GOODMAN

KEYSTONE

KLIMAIRE

KOLDFRONT

MAYTAG

MIDEA

MIRAGE VENTUS

MR COOL

PANASONIC

POLAR WIND

RAMSOND

RCA

SENVILLE

TAPPAN

TCL

THERMOCORE

TRANE

WESTINGHOUSE

WHIRLPOOL

OTHER BRANDS NOT LISTED HERE